

INTERTEK TESTING SERVICES


Report No.: 0612 542
Model No.: 01001
Sample No.: 1/1

hp Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

MKR 20.250 msec

REF -10.0 dBm AT 10 dB .00 dB

PEAK
LOG
10
dB/



WA SB
SC FS
CORR

Tested By: *hewlett*
(Chan Ho Yin)

Date: 13/06/2006

Checked By: *Gary Li*
(Gary Li)

Date: 20/6/06

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

INTERTEK TESTING SERVICES

Report No.: 0612542
Model No.: 01001
Sample No.: V1



Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

MKR 20.175 msec

REF -10.0 dBm

AT 10 dB


.00 dB

PEAK

LOG

10

dB/



Tested By: kan
(Chan Ho Ym)

Date: 13/06/2006

Checked By: Gary Li

Date: 20/6/06

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0612542
Model No.: 01001
Sample No.: 1/1



Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


MKR 1.7250 msec

REF -10.0 dBm

AT 10 dB

-3.49 dB

PEAK
LOG
10
dB/



WA SB
SC FS
CORR

Tested By: Ken
(Ken Ho Kim)

Date: 13/06/2006

Checked By: Gary Li

Date: 20/6/06

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0612542
Model No.: 01001
Sample No.: 1/1

hp Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


MKR 600.00 μ sec

REF -10.0 dBm

AT 10 dB

-3.44 dB

PEAK
LOG
10
dB/



Tested By: [Signature]
(Ben Ho Yin)

Date: 12/06/2006

Checked By: [Signature]
(Gary Li)

Date: 20/6/06

Test Result : Pass / Fail / NA

CENTER 27.146 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec