

MARK-IV VHF BROADBAND SIGNAL BOOSTER
M4BBDAV
FCC ID: TCJ- M4BBDAV

REVISION 0
SUBMITTED BY:


CANAM TECHNOLOGY, INC.

April, 2015



FCC ID: TCJ-M4BBDAV
MODEL: M4BBDAV

I. Label Pictures



FCC Label Location

Model and Serial Number
Label Location

Figure 1 – Labels Location Rear Panel details

Part 90 Signal Boosters	THIS IS A 90.219 CLASS B DEVICE
WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.	

Figure 2 – FC C ID Label design example

NOTE: This is a FCC Label sample.