

**BINATONE TELECOM PLC**

1 Apsley Way London NW2 7HF, United Kingdom.  
Tel: +44(0) 20 8955 2700 Fax: +44(0) 20 8344 8877  
e-mail: [binatoneuk@binatonetelecom.co.uk](mailto:binatoneuk@binatonetelecom.co.uk)



18 Sept, 2017

**Application for Permissive Change of FCC ID: VLJ-MBP38SPU, IC : 4522A-MBP38SPU**

Dear Sir/Madam:

The purpose of this document is to describe all the changes made on the certified transmitter with FCC ID: VLJ-MBP38SPU, IC: 4522A-MBP38SPU

**Modification:**

- Replace the rechargeable Battery.
- Replace the Battery charging IC.
- There is change in the size of the battery compartment.
- There is a minor change in the PCB layout to fit the new battery charging IC.
- Add some de-coupling capacitor at LCD signal.
- Remove the ferrite bead on the AC-DC adaptor.

**Similarities between the certified equipment :**

- No change in the RF part. RF IC, RF circuit, PCB layout of the RF circuit, RF Antennas are identical to the certified equipment.
- MCU are identical to the certified equipment.
- Functionality and intended usage are identical to the certified equipment.
- Outlook is identical to the certified equipment.
- Rating is identical to the certified equipment.

Sincerely,

A handwritten signature in black ink, appearing to be "KH Mueller", written over a horizontal line.

**(Grantee contact signature)**

Name: Karl Heinz Mueller  
Title: Chief Technical Officer