



5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 13.JUL.2026 02:41:24

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 13.JUL.2026 02:42:10

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 13.JUL.2026 02:42:56

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 13.JUL.2026 02:44:21

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 13.JUL.2026 02:45:07

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 13.JUL.2026 02:45:51


15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




15MHz_High_QPSK_1@0(30MHz~18.55GHz)




20MHz_Low_QPSK_1@0(30MHz~18.55GHz)



20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




20MHz_High_QPSK_1@0(30MHz~18.55GHz)




LTE Band 7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~1GHz)




5MHz_Low_QPSK_1@0(1GHz~15GHz)




5MHz_Low_QPSK_1@0(15GHz~25.025GHz)




5MHz_Middle_QPSK_1@0(30MHz~1GHz)




5MHz_Middle_QPSK_1@0(1GHz~15GHz)



5MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:15:03

5MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:15:21

5MHz_High_QPSK_1@0(15GHz~25.675GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:15:39

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:16:24

10MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:16:41

10MHz_Low_QPSK_1@0(15GHz~25.05GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:16:58

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:17:16

10MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:17:34

10MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:17:53

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:18:11

10MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:18:30

10MHz_High_QPSK_1@0(15GHz~25.65GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:18:49


15MHz_Low_QPSK_1@0(30MHz~1GHz)




15MHz_Low_QPSK_1@0(1GHz~15GHz)




15MHz_Low_QPSK_1@0(15GHz~25.075GHz)




15MHz_Middle_QPSK_1@0(30MHz~1GHz)




15MHz_Middle_QPSK_1@0(1GHz~15GHz)



15MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:21:24

15MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:21:42

15MHz_High_QPSK_1@0(15GHz~25.625GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:59:02

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:25:18

20MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:25:35

20MHz_Low_QPSK_1@0(15GHz~25.1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 06:01:15

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:26:08

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:26:25

20MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:26:41

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:26:58

20MHz_High_QPSK_1@0(1GHz~15GHz)



ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 13:27:08

20MHz_High_QPSK_1@0(15GHz~25.6GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:27:31

LTE Band 38, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:28:23

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 13:23:07

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:29:15

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:30:20

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:30:43

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:31:05

15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:32:41

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:33:05

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:33:29

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:38:23

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:38:49

20MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 06:02:43


LTE Band 41, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




5MHz_High_QPSK_1@0(30MHz~27.9GHz)




10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



10MHz_High_QPSK_1@0(30MHz~27.9GHz)




15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:43:38

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:44:02

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:44:28

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:49:58

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:50:24

20MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 05:50:49


LTE Band 66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:36:06

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:36:29

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:36:51

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:37:44

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:38:07

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:38:29

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:39:19

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:39:41

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:40:03

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:40:54

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:41:18

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602U64660E-RF Tester:Loge Long
Date: 14.JUL.2026 04:41:40

**** END ****