



10MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:53:54

10MHz_Low_QPSK_50@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:54:34

10MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:55:14

10MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:55:54

10MHz_High_QPSK_1@49




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:56:35

10MHz_High_QPSK_50@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:57:16

10MHz_High_16QAM_1@49




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:57:56

10MHz_High_16QAM_27@23




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 09:59:18

15MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:00:12

15MHz_Low_QPSK_75@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:01:03

15MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:01:54

15MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:02:47

15MHz_High_QPSK_1@74




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:03:39

15MHz_High_QPSK_75@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:04:30

15MHz_High_16QAM_1@74




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:05:21

15MHz_High_16QAM_27@48




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:07:04

20MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:08:08

20MHz_Low_QPSK_100@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:09:10

20MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:10:10

20MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:11:10

20MHz_High_QPSK_1@99




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:12:10

20MHz_High_QPSK_100@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:13:10

20MHz_High_16QAM_1@99



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:14:10


20MHz_High_16QAM_27@73



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:16:11


Band 7, Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:51:46

5MHz_Low_QPSK_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:52:06

5MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 21:38:28

5MHz_Low_16QAM_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:52:49

5MHz_High_QPSK_1@24




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:53:12

5MHz_High_QPSK_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:53:44

5MHz_High_16QAM_1@24




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:54:16

5MHz_High_16QAM_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:54:47

10MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:55:11

10MHz_Low_QPSK_50@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:55:32

10MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:55:53

10MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:56:13

10MHz_High_QPSK_1@49




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:56:32

10MHz_High_QPSK_50@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:57:12

10MHz_High_16QAM_1@49




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:57:52

10MHz_High_16QAM_27@23




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:59:12

15MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:59:35

15MHz_Low_QPSK_75@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 10:59:55

15MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:00:15

15MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:00:35

15MHz_High_QPSK_1@74




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:00:54

15MHz_High_QPSK_75@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:01:45

15MHz_High_16QAM_1@74




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:02:36

15MHz_High_16QAM_27@48




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:04:17

20MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:04:42

20MHz_Low_QPSK_100@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:05:03

20MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:05:25

20MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:05:48

20MHz_High_QPSK_1@99




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:06:10

20MHz_High_QPSK_100@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:07:13

20MHz_High_16QAM_1@99




20MHz_High_16QAM_27@73




Band 66, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0



1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 21:46:10

1.4MHz_High_QPSK_6@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:13:30

1.4MHz_High_16QAM_1@5




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 21:54:27

1.4MHz_High_16QAM_6@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:14:26

3MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 21:56:19

3MHz_Low_QPSK_15@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:15:33

3MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 21:57:48

3MHz_Low_16QAM_15@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:16:37

3MHz_High_QPSK_1@14




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 21:59:15

3MHz_High_QPSK_15@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:17:44

3MHz_High_16QAM_1@14




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 22:00:42

3MHz_High_16QAM_15@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:18:53

5MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 22:02:00

5MHz_Low_QPSK_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:20:00

5MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 22:03:15

5MHz_Low_16QAM_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:21:02

5MHz_High_QPSK_1@24




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 22:04:44

5MHz_High_QPSK_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:22:04

5MHz_High_16QAM_1@24




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 22:05:57

5MHz_High_16QAM_25@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:23:05

10MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:23:48

10MHz_Low_QPSK_50@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:24:28

10MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:25:07

10MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:25:47

10MHz_High_QPSK_1@49




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:26:27

10MHz_High_QPSK_50@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:27:07

10MHz_High_16QAM_1@49




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:27:48

10MHz_High_16QAM_27@23




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:29:11

15MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:30:05

15MHz_Low_QPSK_75@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:30:56

15MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:31:47

15MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:32:38

15MHz_High_QPSK_1@74




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:33:29

15MHz_High_QPSK_75@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:34:20

15MHz_High_16QAM_1@74




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:35:12

15MHz_High_16QAM_27@48




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:36:50

20MHz_Low_QPSK_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:37:54

20MHz_Low_QPSK_100@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:38:55

20MHz_Low_16QAM_1@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:39:55

20MHz_Low_16QAM_27@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:40:56

20MHz_High_QPSK_1@99




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:41:56

20MHz_High_QPSK_100@0




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:42:58

20MHz_High_16QAM_1@99



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:43:59

20MHz_High_16QAM_27@73




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 25.NOV.2025 11:46:04

Spurious Emissions at Antenna Terminal

FCC Part 22H


Band 5, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:16:48

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:15:06

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:15:23

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:15:42

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:15:00

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:15:18

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:58:38

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:58:55

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:59:14

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:59:34

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:00:12

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:00:48

FCC Part 24E


Band 2, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:39:21

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:39:42

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:40:02

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:40:26

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:41:08

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:41:50

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:42:32

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:43:14

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:43:54

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:44:38

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:45:19

20MHz_High_QPSK_1@0(30MHz~20.1GHz)









ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:45:59


FCC Part 27

Band 4, Normal

1RB was the worst case




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:49:07

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:49:28

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:49:49

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:50:13

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:50:57

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:51:39

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:52:23

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:53:02

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:53:42

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:54:25

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:55:05

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 22:55:45


Band 7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 12.DEC.2025 14:21:30

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:19:27

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 12.DEC.2025 14:22:10

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:20:58

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 12.DEC.2025 14:13:37

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:22:25


Band 66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:03:54

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:04:15

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:04:35

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:04:57

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:05:38

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:06:17

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:07:00

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:07:40

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:08:21

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:09:05

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:09:49

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502Z02203E-RF Tester:Loge Long
Date: 24.NOV.2025 23:10:33

***** END *****