




5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




5MHz_High_QPSK_1@0(30MHz~9.49GHz)




10MHz_Low_QPSK_1@0(30MHz~9.49GHz)



10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




10MHz_High_QPSK_1@0(30MHz~9.49GHz)



FCC Part 24E


LTE Band 2, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 13.MAY.2025 11:09:06

1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 10.MAY.2025 23:20:29

1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 10.MAY.2025 23:20:55

3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 10.MAY.2025 23:22:15

3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 10.MAY.2025 23:22:41

3MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 10.MAY.2025 23:23:07


5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




5MHz_High_QPSK_1@0(30MHz~20.1GHz)




10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




10MHz_High_QPSK_1@0(30MHz~20.1GHz)




15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




15MHz_High_QPSK_1@0(30MHz~20.1GHz)




20MHz_Low_QPSK_1@0(30MHz~20.1GHz)



20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




20MHz_High_QPSK_1@0(30MHz~20.1GHz)



FCC Part 27


LTE Band 4, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 08:30:18

1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 08:30:36

1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 08:30:54

3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 08:31:52

3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 08:32:11

3MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 08:32:29


5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




5MHz_High_QPSK_1@0(30MHz~18.55GHz)




10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




10MHz_High_QPSK_1@0(30MHz~18.55GHz)




15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




15MHz_High_QPSK_1@0(30MHz~18.55GHz)




20MHz_Low_QPSK_1@0(30MHz~18.55GHz)



20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




20MHz_High_QPSK_1@0(30MHz~18.55GHz)




LTE Band 7, Normal
 1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 09:13:58

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 09:14:18

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 09:14:37

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 09:15:55

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 09:18:32

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 09:18:53


15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




15MHz_High_QPSK_1@0(30MHz~27.2GHz)




20MHz_Low_QPSK_1@0(30MHz~26.7GHz)



20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




20MHz_High_QPSK_1@0(30MHz~26.7GHz)




LTE Band 38, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 09:45:45

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 09:46:18

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 09:46:49

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 09:47:53

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 09:48:24

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 09:48:57


15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




15MHz_High_QPSK_1@0(30MHz~27.2GHz)




20MHz_Low_QPSK_1@0(30MHz~27.9GHz)



20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




20MHz_High_QPSK_1@0(30MHz~27.2GHz)




LTE Band 41, Normal
 1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 10:03:03

5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 10:03:34

5MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 10:04:08

10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 10:08:20

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 10:08:54

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
 Date: 12.MAY.2025 10:09:28

15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 10:11:18

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 10:11:52

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 10:12:24

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 10:23:25

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 10:23:57

20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2502S55753E-RF Tester:Loge Long
Date: 12.MAY.2025 10:24:28

***** END *****