



LTE Band 38, Normal


5MHz_Middle_QPSK_25@0




5MHz_Middle_16QAM_25@0




10MHz_Middle_QPSK_50@0




10MHz_Middle_16QAM_50@0



15MHz_Middle_QPSK_75@0




15MHz_Middle_16QAM_75@0




20MHz_Middle_QPSK_100@0

20MHz_Middle_16QAM_100@0



ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 11.MAY.2026 20:43:55




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 11.MAY.2026 20:41:41

Spurious Emissions at Antenna Terminal


FCC Part 22H

LTE Band 5, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



3MHz_High_QPSK_1@0(30MHz~9.49GHz)




5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 04:10:44

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 04:11:18

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 04:11:53

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 04:12:56

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 04:13:32

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 04:14:11


FCC Part 24E

LTE Band 2, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:21:54

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:22:53

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:24:42

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:31:27

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:35:29

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:40:50

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:42:25

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:43:23

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:44:18

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:45:43

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:46:39

20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:47:38


FCC Part 27

LTE Band 4, Normal

1RB was the worst case




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:55:55

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:56:56

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:57:55

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 02:59:18

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:00:12

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:01:04

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:02:25

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:03:18

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:04:15

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:05:41

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:06:36

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S53473E-RF Tester:Permin Fu
Date: 12.MAY.2026 03:07:34


LTE Band 7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S53473E-RF Tester:Fermin Fu
Date: 21.MAY.2026 21:47:44

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S53473E-RF Tester:Fermin Fu
Date: 21.MAY.2026 21:49:21

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S53473E-RF Tester:Fermin Fu
Date: 21.MAY.2026 21:52:23

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S53473E-RF Tester:Fermin Fu
Date: 21.MAY.2026 21:53:30

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2602S53473E-RF Tester:Fermin Fu
Date: 21.MAY.2026 21:57:34

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S53473E-RF Tester:Fermin Fu
Date: 21.MAY.2026 22:09:36


LTE Band 38, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




5MHz_High_QPSK_1@0(30MHz~27.2GHz)




10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




10MHz_High_QPSK_1@0(30MHz~27.2GHz)




15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




15MHz_High_QPSK_1@0(30MHz~27.2GHz)




20MHz_Low_QPSK_1@0(30MHz~27.2GHz)



20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



20MHz_High_QPSK_1@0(30MHz~27.2GHz)



***** END *****