

Declaration of Product Change Differences

We Traxxas LP declare that our product TQi Sport TX has below changes to enhance the product performance, others are the same as before SZCR2502000735AT **except** below.

Model/HVIN		Texas (Instruments chip model)	Software Version	Appearance	Detail description
Original	6567	CC2640F128RHBR	15003		Difference- 6567 VS 6506-2CH: 1) Changing model number from 6567 to 6506-2CH 2) Instruments chip model changed: CC2640F128RHBR and CC2640R2LRHBR are same chip, Just replacing old and new chip models. 3) Software Version changed. Difference-6567 VS 6505-2CH: 1) Changing model number from 6567 to 6506-2CH 2) Instruments chip model changed: CC2640F128RHBR and CC2640R2LRHBR are same chip, Just replacing old and new chip models. 3) Software Version changed. 4) Plastic casing is different Difference-6506-2CH VS 6505-2CH: 1) Model Number different. 2) Plastic casing is different
New	6506-2CH	CC2640R2LRHBR	15015		
	6505-2CH	CC2640R2LRHBR	15015		

Model/HVIN		Texas (Instruments chip model)	Software Version	Appearance	Detail description
Original	6568	CC2640F128RHBR	15003		Difference- 6568 VS 6506-3CH: 1) Changing model number from 6568 to 6506-3CH 2) Instruments chip model changed: CC2640F128RHBR and CC2640R2LRHBR are same chip, Just replacing old and new chip models. 3) Software Version changed. Difference-6568 VS 6505-3CH: 1) Changing model number from 6568 to 6505-3CH 2) Instruments chip model changed: CC2640F128RHBR and CC2640R2LRHBR are same chip, Just replacing old and new chip models. 3) Software Version changed. 4) Plastic casing is different Difference-6506-3CH VS 6505-3CH: 1) Model Number different. 2) Plastic casing is different
New	6506-3CH	CC2640R2LRHBR	15015		
	6505-3CH	CC2640R2LRHBR	15015		

Model/HVIN	Texas (Instruments chip model)	Software Version	Appearance	Detail description
6567	CC2640F128RHBR	15003		Difference- 6567 VS 6568 1) 6568 (contains 3 control switches) adds an additional wire harness from the circuit board to a switchboard, while the model 6567 (contains 2 control switches) does not. 2) Practical digital component's location is a bit different.
6568	CC2640F128RHBR	15003		

Remark:

The hardware has not changed and as such the RF performance is also unchanged.

The latest software update allows the transmitter to communicate with the TQ receiver as well as a TQi receiver. Previously it could only communicate with the TQ receivers. This new software allows us to use this long-range transmitter with other vehicles we produce.

RF operation is not impacted, only what data is transmitted to the receivers.

Company Chop: Traxxas LP

Authorized signature: _____



Position: Sr. Manager Electrical Engineering

Date: 2026.04.01