Appendix G: Band edge measurements

Test Result

Test Mode	Antenna	Ch Name	Freq(MHz)	Ref Level [dBm]	Result [dBm]	Limit [dBm]	Verdict
DH5	Ant1	Low	2402	-1.33	-51.05	≤-21.33	PASS
		High	2480	-3.19	-50.49	≤-23.19	PASS
		Low	Hop_2402	-1.90	-50.43	≤-21.9	PASS
		High	Hop_2480	-2.71	-50.26	≤-22.71	PASS
2DH5	Ant1	Low	2402	-2.09	-50.4	≤-22.09	PASS
		High	2480	-3.98	-49.7	≤-23.98	PASS
		Low	Hop_2402	-3.01	-50.39	≤-23.01	PASS
		High	Hop_2480	-3.47	-49.75	≤-23.47	PASS
3DH5	Ant1	Low	2402	-1.26	-50.65	≤-21.26	PASS
		High	2480	-2.96	-51.04	≤-22.96	PASS
		Low	Hop_2402	-2.79	-49.93	≤-22.79	PASS
		High	Hop_2480	-3.45	-50.32	≤-23.45	PASS

Test Graphs

DH5_Ant1_Low_2402



DH5_Ant1_High_2480



DH5_Ant1_Low_Hop_2402



DH5_Ant1_High_Hop_2480



2DH5_Ant1_Low_2402



2DH5_Ant1_High_2480



2DH5_Ant1_Low_Hop_2402



2DH5_Ant1_High_Hop_2480



3DH5_Ant1_Low_2402



3DH5_Ant1_High_2480



3DH5_Ant1_Low_Hop_2402



3DH5_Ant1_High_Hop_2480



Appendix H: Conducted Spurious Emission

Test Result

Test Mode	Antenna	Freq(MHz)	Freq Range [MHz]	Ref Level [dBm]	Result [dBm]	Limit [dBm]	Verdict
DH5	Ant1	2402	30~26500	-1.33	-40.41	≤-21.33	PASS
		2441	30~26500	-2.58	-40.84	≤-22.58	PASS
		2480	30~26500	-3.19	-42.44	≤-23.19	PASS
2DH5	Ant1	2402	30~26500	-2.09	-40.4	≤-22.09	PASS
		2441	30~26500	-2.77	-42.1	≤-22.77	PASS
		2480	30~26500	-3.98	-42.31	≤-23.98	PASS
3DH5	Ant1	2402	30~26500	-1.26	-42.45	≤-21.26	PASS
		2441	30~26500	-2.06	-40.98	≤-22.06	PASS
		2480	30~26500	-2.96	-42.27	≤-22.96	PASS

Test Graphs

DH5_Ant1_2402_30~26500



DH5_Ant1_2441_30~26500

DH5_Ant1_2480_30~26500



2DH5_Ant1_2402_30~26500



2DH5_Ant1_2441_30~26500



2DH5_Ant1_2480_30~26500



3DH5_Ant1_2402_30~26500



3DH5_Ant1_2441_30~26500



3DH5_Ant1_2480_30~26500



14. TEST SETUP PHOTO

Conducted Test

Radiated Test (Below 1GHz)



Radiated Test (Above 1GHz)

15. EUT PHOTO

External Photos

M/N: CVM8

External Photos

M/N: CVM8

External Photos

M/N: CVM8



External Photos

M/N: CVM8

External Photos

M/N: CVM8



Internal Photos

M/N: CVM8





Internal Photos

M/N: CVM8



Internal Photos

M/N: CVM8





Internal Photos

M/N: CVM8





Internal Photos

M/N: CVM8





Internal Photos

M/N: CVM8



Internal Photos

M/N: CVM8





Internal Photos

M/N: CVM8





Internal Photos

M/N: CVM8





Internal Photos

M/N: CVM8





End of Test Report