

11N40SISO-Ant1-2437-0~Reference-PASS



11N40SISO-Ant1-2437-30~1000-PASS



11N40SISO-Ant1-2437-1000~26500-PASS



11N40SISO-Ant1-2452-0~Reference-PASS



11N40SISO-Ant1-2452-30~1000-PASS



11N40SISO-Ant1-2452-1000~26500-PASS

11AX20SISO-Ant1-2412-0~Reference-PASS



11AX20SISO-Ant1-2412-30~1000-PASS



11AX20SISO-Ant1-2412-1000~26500-PASS

11AX20SISO-Ant1-2437-0~Reference-PASS



11AX20SISO-Ant1-2437-30~1000-PASS



11AX20SISO-Ant1-2437-1000~26500-PASS

11AX20SISO-Ant1-2462-0~Reference-PASS



11AX20SISO-Ant1-2462-30~1000-PASS



11AX20SISO-Ant1-2462-1000~26500-PASS

11AX40SISO-Ant1-2422-0~Reference-PASS



11AX40SISO-Ant1-2422-30~1000-PASS



11AX40SISO-Ant1-2422-1000~26500-PASS



11AX40SISO-Ant1-2437-0~Reference-PASS



11AX40SISO-Ant1-2437-30~1000-PASS



11AX40SISO-Ant1-2437-1000~26500-PASS



11AX40SISO-Ant1-2452-0~Reference-PASS



11AX40SISO-Ant1-2452-30~1000-PASS



11AX40SISO-Ant1-2452-1000~26500-PASS

A.5 MAXIMUM POWER SPECTRAL DENSITY

TestMode	Antenna	Frequency[MHz]	Result[dBm/3-100kHz]	Limit[dBm/3kHz]	Verdict
11B	Ant1	2412	-8.23	≤8.00	PASS
11B	Ant1	2437	-8.87	≤8.00	PASS
11B	Ant1	2462	-7.02	≤8.00	PASS
11G	Ant1	2412	-9.51	≤8.00	PASS
11G	Ant1	2437	-8.93	≤8.00	PASS
11G	Ant1	2462	-8.95	≤8.00	PASS
11N20SISO	Ant1	2412	-8.34	≤8.00	PASS
11N20SISO	Ant1	2437	-8.96	≤8.00	PASS
11N20SISO	Ant1	2462	-8.15	≤8.00	PASS
11N40SISO	Ant1	2422	-11.76	≤8.00	PASS
11N40SISO	Ant1	2437	-10.56	≤8.00	PASS
11N40SISO	Ant1	2452	-12.00	≤8.00	PASS
11AX20SISO	Ant1	2412	-9.33	≤8.00	PASS
11AX20SISO	Ant1	2437	-9.82	≤8.00	PASS
11AX20SISO	Ant1	2462	-10.01	≤8.00	PASS
11AX40SISO	Ant1	2422	-12.90	≤8.00	PASS
11AX40SISO	Ant1	2437	-12.57	≤8.00	PASS
11AX40SISO	Ant1	2452	-12.49	≤8.00	PASS



11B-Ant1-2412-PASS

11B-Ant1-2437-PASS



11B-Ant1-2462-PASS



11G-Ant1-2412-PASS



11G-Ant1-2437-PASS



11G-Ant1-2462-PASS



11N20SISO-Ant1-2412-PASS



11N20SISO-Ant1-2437-PASS



11N20SISO-Ant1-2462-PASS



11N40SISO-Ant1-2422-PASS



11N40SISO-Ant1-2437-PASS



11N40SISO-Ant1-2452-PASS



11AX20SISO-Ant1-2412-PASS



11AX20SISO-Ant1-2437-PASS



11AX20SISO-Ant1-2462-PASS



11AX40SISO-Ant1-2422-PASS



11AX40SISO-Ant1-2437-PASS



11AX40SISO-Ant1-2452-PASS

APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

*** End of Report ***

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.