







5. Spurious Emission


Global United Technology Services Co., Ltd.



No. 123-128, Tower A, Jinyuan Business Building, No.2, Laodong Industrial Zone,



Xixiang Road, Baoan District, Shenzhen, Guangdong, China 518102



Telephone: +86 (0) 755 2779 8480 Fax: +86 (0) 755 2779 8960



5.1 1.4M Bandwidth Test Graph




























5.1 3M Bandwidth Test Graph



Global United Technology Services Co., Ltd.



No. 123-128, Tower A, Jinyuan Business Building, No.2, Laodong Industrial Zone,



Xixiang Road, Baoan District, Shenzhen, Guangdong, China 518102



Telephone: +86 (0) 755 2779 8480 Fax: +86 (0) 755 2779 8960




























5.1 5M Bandwidth Test Graph



Global United Technology Services Co., Ltd.



No. 123-128, Tower A, Jinyuan Business Building, No.2, Laodong Industrial Zone,



Xixiang Road, Baoan District, Shenzhen, Guangdong, China 518102



Telephone: +86 (0) 755 2779 8480 Fax: +86 (0) 755 2779 8960




























5.1 10M Bandwidth Test Graph



Global United Technology Services Co., Ltd.



No. 123-128, Tower A, Jinyuan Business Building, No.2, Laodong Industrial Zone,



Xixiang Road, Baoan District, Shenzhen, Guangdong, China 518102



Telephone: +86 (0) 755 2779 8480 Fax: +86 (0) 755 2779 8960





























5.1 15M Bandwidth Test Graph



Global United Technology Services Co., Ltd.



No. 123-128, Tower A, Jinyuan Business Building, No.2, Laodong Industrial Zone,



Xixiang Road, Baoan District, Shenzhen, Guangdong, China 518102



Telephone: +86 (0) 755 2779 8480 Fax: +86 (0) 755 2779 8960





























5.1 20M Bandwidth Test Graph



Global United Technology Services Co., Ltd.



No. 123-128, Tower A, Jinyuan Business Building, No.2, Laodong Industrial Zone,



Xixiang Road, Baoan District, Shenzhen, Guangdong, China 518102



Telephone: +86 (0) 755 2779 8480 Fax: +86 (0) 755 2779 8960



























-----End-----