



11AX40MIMO_5310



Date: 28.OCT.2021 16:32:29


11AX20MIMO_5320



Date: 28.OCT.2021 16:25:18


ETH2:

11A_Ant0_5180




Date: 27.OCT.2021 12:09:22

11A_Ant0_5200




Date: 27.OCT.2021 12:11:02

11A_Ant0_5240




Date: 27.OCT.2021 12:12:44

11A_Ant0_5260




Date: 27.OCT.2021 12:14:37

11A_Ant0_5280




Date: 27.OCT.2021 12:16:19

11A_Ant0_5320




Date: 27.OCT.2021 12:17:55

11A_Ant0_5500




Date: 27.OCT.2021 12:19:43

11A Ant0 5580




Date: 27.OCT.2021 12:21:32

11A Ant0 5700




Date: 27.OCT.2021 12:27:08

11A Ant0 5720




Date: 27.OCT.2021 12:30:29

11A Ant0 5745




Date: 27.OCT.2021 12:33:08

11A Ant0 5785




Date: 27.OCT.2021 12:35:54

11A Ant0 5825




Date: 27.OCT.2021 12:38:03

11N20SISO_Ant0_5180




Date: 27.OCT.2021 12:40:47

11N20SISO_Ant0_5200




Date: 27.OCT.2021 12:42:14

11N20SISO_Ant0_5240




Date: 27.OCT.2021 12:43:47

11N20SISO_Ant0_5260




Date: 27.OCT.2021 12:45:21

11N20SISO_Ant0_5280




Date: 27.OCT.2021 12:47:05

11N20SISO_Ant0_5320




Date: 27.OCT.2021 12:48:48

11N20SISO_Ant0_5500




Date: 27.OCT.2021 12:51:52

11N20SISO_Ant0_5580




Date: 27.OCT.2021 12:53:39

11N20SISO_Ant0_5700




Date: 27.OCT.2021 12:55:32

11N20SISO_Ant0_5720




Date: 27.OCT.2021 12:57:15

11N20SISO_Ant0_5745




Date: 27.OCT.2021 12:59:06

11N20SISO_Ant0_5785




Date: 27.OCT.2021 14:34:59

11N20SISO_Ant0_5825




Date: 27.OCT.2021 14:36:52

11N40SISO_Ant0_5190




Date: 27.OCT.2021 14:39:25

11N40SISO_Ant0_5230




Date: 27.OCT.2021 14:41:18

11N40SISO_Ant0_5270




Date: 27.OCT.2021 14:43:10

11N40SISO_Ant0_5310




Date: 27.OCT.2021 14:45:06

11N40SISO_Ant0_5510




Date: 27.OCT.2021 14:46:57

11N40SISO_Ant0_5550




Date: 27.OCT.2021 14:49:20

11N40SISO_Ant0_5670




Date: 27.OCT.2021 14:51:53

11N40SISO_Ant0_5710




Date: 27.OCT.2021 14:53:37

11N40SISO_Ant0_5755




Date: 27.OCT.2021 14:55:36

11N40SISO_Ant0_5795




Date: 27.OCT.2021 14:57:35

11AC20SISO_Ant0_5180




Date: 27.OCT.2021 14:59:32

11AC20SISO_Ant0_5200




Date: 27.OCT.2021 15:01:20

11AC20SISO_Ant0_5240




Date: 27.OCT.2021 15:02:48

11AC20SISO_Ant0_5260




Date: 27.OCT.2021 15:04:35

11AC20SISO_Ant0_5280




Date: 27.OCT.2021 15:06:06

11AC20SISO_Ant0_5320




Date: 27.OCT.2021 15:07:50

11AC20SISO_Ant0_5500




Date: 27.OCT.2021 15:09:28

11AC20SISO_Ant0_5580




Date: 27.OCT.2021 15:11:15

11AC20SISO_Ant0_5700




Date: 27.OCT.2021 15:12:41

11AC20SISO_Ant0_5720




Date: 27.OCT.2021 15:14:09

11AC20SISO_Ant0_5745




Date: 27.OCT.2021 15:20:31

11AC20SISO_Ant0_5785




Date: 27.OCT.2021 15:22:47

11AC20SISO_Ant0_5825




Date: 27.OCT.2021 15:24:33

11AC40SISO_Ant0_5190




Date: 27.OCT.2021 15:31:19

11AC40SISO_Ant0_5230




Date: 27.OCT.2021 15:33:33

11AC40SISO_Ant0_5270




Date: 27.OCT.2021 15:35:04

11AC40SISO_Ant0_5310




Date: 27.OCT.2021 15:37:50

11AC40SISO_Ant0_5510




Date: 27.OCT.2021 18:57:18

11AC40SISO_Ant0_5550




Date: 27.OCT.2021 18:59:53

11AC40SISO_Ant0_5670




Date: 27.OCT.2021 19:01:33

11AC40SISO_Ant0_5710




Date: 27.OCT.2021 19:03:46

11AC40SISO_Ant0_5755




Date: 27.OCT.2021 19:07:54

11AC40SISO_Ant0_5795




Date: 27.OCT.2021 19:10:01

11AC80SISO_Ant0_5210




Date: 27.OCT.2021 19:12:11

11AC80SISO_Ant0_5290




Date: 27.OCT.2021 19:14:10

11AC80SISO_Ant0_5530




Date: 27.OCT.2021 19:16:02

11AC80SISO_Ant0_5610




Date: 27.OCT.2021 19:18:21

11AC80SISO_Ant0_5690




Date: 27.OCT.2021 19:20:11

11AC80SISO_Ant0_5775




Date: 27.OCT.2021 19:22:41

11AX20SISO_Ant0_5180




Date: 27.OCT.2021 19:46:22

11AX40SISO_Ant0_5190




Date: 27.OCT.2021 21:06:25

11AX20SISO Ant0 5200




Date: 27.OCT.2021 19:48:14

11AX80SISO Ant0 5210




Date: 27.OCT.2021 21:26:36

11AX40SISO Ant0 5230




Date: 27.OCT.2021 21:08:08

11AX20SISO Ant0 5240




Date: 27.OCT.2021 19:49:50

11AX20SISO Ant0 5260




Date: 27.OCT.2021 19:51:52

11AX40SISO Ant0 5270




Date: 27.OCT.2021 21:09:47

11AX20SISO Ant0 5280




Date: 27.OCT.2021 19:54:22

11AX80SISO Ant0 5290




Date: 27.OCT.2021 21:29:12

11AX40SISO Ant0 5310




Date: 27.OCT.2021 21:11:20

11AX20SISO Ant0 5320




Date: 27.OCT.2021 19:56:24

11AX20SISO Ant0 5500




Date: 27.OCT.2021 19:58:14

11AX40SISO Ant0 5510




Date: 27.OCT.2021 21:13:27

11AX80SISO Ant0 5530




Date: 27.OCT.2021 21:32:01

11AX40SISO Ant0 5550




Date: 27.OCT.2021 21:15:13

11AX20SISO Ant0 5580




Date: 27.OCT.2021 19:59:57

11AX80SISO Ant0 5610




Date: 27.OCT.2021 21:36:15

11AX40SISO Ant0 5670




Date: 27.OCT.2021 21:17:05

11AX80SISO Ant0 5690




Date: 27.OCT.2021 21:38:46

11AX20SISO Ant0 5700




Date: 27.OCT.2021 20:01:52

11AX40SISO Ant0 5710




Date: 27.OCT.2021 21:19:16

11AX20SISO Ant0 5720




Date: 27.OCT.2021 20:57:13

11AX20SISO Ant0 5745




Date: 27.OCT.2021 20:59:27

11AX40SISO Ant0 5755




Date: 27.OCT.2021 21:21:53

11AX80SISO Ant0 5775




Date: 27.OCT.2021 21:44:58

11AX20SISO Ant0 5785




Date: 27.OCT.2021 21:01:53

11AX40SISO Ant0 5795




Date: 27.OCT.2021 21:24:07

11AX20SISO Ant0 5825




Date: 27.OCT.2021 21:03:52

11A Ant1 5180



Date: 25.OCT.2021 14:55:12

11A Ant1 5200



Date: 25.OCT.2021 14:57:12

11A Ant1 5240