

Label & Label Location

FCC ID label in the paper design format

		耳内式蓝牙助听器	
产品名称:耳内式蓝牙助听器 工作电源:DC 3.7V			
注册人/生产企业/售后: 名称:广州市行动者科技有限责任公司 住所:广州市荔湾区荔湾路94号A楼601 生产地址:广州市花都区坪山工业园7号花山厂房1号楼6楼 售后服务热线:+86 20 81179170			
产品型号:	XDZ-H20T	FCC ID: 2A4IK-H20T	
使用期限:	3年	 UPC: XXXXXXXXXXXXX	
生产日期:	2022.12.12		
生产批次:	XXXXXXXXXXXX		
注册证编号:	粤械注准XXXXXXXXXX		
产品技术要求编号:	粤械注准XXXXXXXXXX		
生产许可证编号:	粤食药监械生产许XXXXXXXX号	 SN: XXXXXXXXXXXXX	
广州市行动者科技有限责任公司 电话: +86 20 81179170 传真: +86 20 81179171 邮箱: cs@opsmen.com / info@opsmen.com 网 址: www.earmor.com 办事处地址: 广东省广州市荔湾区荔湾路94号A601室			

FCC ID label in the formal user's manual of the product

1. Vandalism, disassembly, modification of this product
2. Product damage caused by wrong operation

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

FCC ID: 2A4IK-H20T

