



Please refer to following plots:

B48-5M-CSE-L-QPSK-30MHz-10GHz




Date: 20.SEP.2022 17:11:58

B48-5M-CSE-L-QPSK-10GHz-25GHz




Date: 20.SEP.2022 17:12:23

B48-5M-CSE-L-QPSK-25GHz-37GHz




Date: 20.SEP.2022 17:12:49

B48-5M-CSE-M-QPSK-30MHz-10GHz




Date: 20.SEP.2022 17:29:19

B48-5M-CSE-M-QPSK-10GHz-25GHz




Date: 20.SEP.2022 17:29:45

B48-5M-CSE-M-QPSK-25GHz-37GHz




Date: 20.SEP.2022 17:30:10

B48-5M-CSE-H-QPSK-30MHz-10GHz




Date: 20.SEP.2022 17:46:53

B48-5M-CSE-H-QPSK-10GHz-25GHz




Date: 20.SEP.2022 17:47:18

B48-5M-CSE-H-QPSK-25GHz-37GHz




Date: 20.SEP.2022 17:47:44

B48-10M-CSE-L-QPSK-30MHz-10GHz




Date: 20.SEP.2022 15:34:28

B48-10M-CSE-L-QPSK-10GHz-25GHz




Date: 20.SEP.2022 11:16:36

B48-10M-CSE-L-QPSK-25GHz-37GHz




Date: 20.SEP.2022 11:17:04

B48-10M-CSE-M-QPSK-30MHz-10GHz




Date: 20.SEP.2022 15:56:57

B48-10M-CSE-M-QPSK-10GHz-25GHz




Date: 20.SEP.2022 11:31:46

B48-10M-CSE-M-QPSK-25GHz-37GHz




Date: 20.SEP.2022 11:32:15

B48-10M-CSE-H-QPSK-30MHz-10GHz




Date: 20.SEP.2022 15:48:15

B48-10M-CSE-H-QPSK-10GHz-25GHz




Date: 20.SEP.2022 11:53:26

B48-10M-CSE-H-QPSK-25GHz-37GHz




Date: 20.SEP.2022 11:53:54

B48-15M-CSE-L-QPSK-30MHz-10GHz




Date: 20.SEP.2022 16:12:31

B48-15M-CSE-L-QPSK-10GHz-25GHz




Date: 20.SEP.2022 16:12:57

B48-15M-CSE-L-QPSK-25GHz-37GHz




Date: 20.SEP.2022 16:13:24

B48-15M-CSE-M-QPSK-30MHz-10GHz




Date: 20.SEP.2022 16:31:49

B48-15M-CSE-M-QPSK-10GHz-25GHz




Date: 20.SEP.2022 16:32:18

B48-15M-CSE-M-QPSK-25GHz-37GHz




Date: 20.SEP.2022 16:32:43

B48-15M-CSE-H-QPSK-30MHz-10GHz




Date: 20.SEP.2022 16:50:04

B48-15M-CSE-H-QPSK-10GHz-25GHz




Date: 20.SEP.2022 16:50:30

B48-15M-CSE-H-QPSK-25GHz-37GHz




Date: 20.SEP.2022 16:50:55

B48-20M-CSE-L-QPSK-30MHz-10GHz




Date: 20.SEP.2022 14:56:43

B48-20M-CSE-L-QPSK-10GHz-25GHz




Date: 20.SEP.2022 13:57:44

B48-20M-CSE-L-QPSK-25GHz-37GHz




Date: 20.SEP.2022 13:58:13

B48-20M-CSE-M-QPSK-30MHz-10GHz




Date: 20.SEP.2022 15:10:14

B48-20M-CSE-M-QPSK-10GHz-25GHz




Date: 20.SEP.2022 14:13:43

B48-20M-CSE-M-QPSK-25GHz-37GHz




Date: 20.SEP.2022 14:14:11

B48-20M-CSE-H-QPSK-30MHz-10GHz




Date: 20.SEP.2022 14:40:04

B48-20M-CSE-H-QPSK-10GHz-25GHz



Date: 20.SEP.2022 14:40:32

B48-20M-CSE-H-QPSK-25GHz-37GHz



Date: 20.SEP.2022 14:41:00