



2_20MHz_Low_16QAM_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 23.MAY.2024 22:03:11

2_20MHz_Low_16QAM_100@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 23.MAY.2024 22:03:53

2_20MHz_High_QPSK_1@99




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 23.MAY.2024 21:51:55

2_20MHz_High_QPSK_100@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 23.MAY.2024 21:52:40

2_20MHz_High_16QAM_1@99



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 23.MAY.2024 21:53:26

2_20MHz_High_16QAM_100@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 23.MAY.2024 21:54:11

Spurious Emissions at Antenna Terminal

FCC Part 22H


B5 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:03:02

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:03:59

1.4MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:04:56

3MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:06:13

3MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:07:11

3MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:08:09

5MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:09:26

5MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:10:24

5MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:11:19

10MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:12:32

10MHz_Middle_QPSK_1@0



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:13:30

10MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:14:32


FCC Part 24E

B2 , Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0




1.4MHz_Middle_QPSK_1@0




1.4MHz_High_QPSK_1@0




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0



3MHz_High_QPSK_1@0




5MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:23:01

5MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:24:02

5MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:25:01

10MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:26:20

10MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:27:20

10MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:28:21

15MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:29:41

15MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:30:41

15MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:31:41

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 22.MAY.2024 13:48:20

20MHz_Middle_QPSK_1@0



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:34:01

20MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:35:40


FCC Part 27

B4 , Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0




1.4MHz_Middle_QPSK_1@0




1.4MHz_High_QPSK_1@0




3MHz_Low_QPSK_1@0




3MHz_Middle_QPSK_1@0



3MHz_High_QPSK_1@0(30MHz~18.55GHz)




5MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:47:39

5MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:48:39

5MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:49:41

10MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:52:56

10MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:53:58

10MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:54:57

15MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:56:14

15MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:57:15

15MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:58:15

20MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 19:59:35

20MHz_Middle_QPSK_1@0



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:00:38


20MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:01:41

B38 , Normal
1RB was the worst case


5MHz_Low_QPSK_1@0




5MHz_Middle_QPSK_1@0




5MHz_High_QPSK_1@0




10MHz_Low_QPSK_1@0




10MHz_Middle_QPSK_1@0



10MHz_High_QPSK_1@0




15MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:00:16

15MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:01:30

15MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:02:42

20MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:04:18

20MHz_Middle_QPSK_1@0



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:05:28


20MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:06:39

B7 , Normal
1RB was the worst case


5MHz_Low_QPSK_1@0




5MHz_Middle_QPSK_1@0




5MHz_High_QPSK_1@0




10MHz_Low_QPSK_1@0




10MHz_Middle_QPSK_1@0



10MHz_High_QPSK_1@0




15MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:23:31

15MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:24:40

15MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:25:50

20MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:28:08

20MHz_Middle_QPSK_1@0



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:29:19


20MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 20:30:31

B41_2 , Normal
1RB was the worst case


2_5MHz_Low_QPSK_1@0




2_5MHz_Middle_QPSK_1@0




2_5MHz_High_QPSK_1@0




2_10MHz_Low_QPSK_1@0




2_10MHz_Middle_QPSK_1@0



2_10MHz_High_QPSK_1@0




2_15MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:31:37

2_15MHz_Middle_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:32:17

2_15MHz_High_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:32:58

2_20MHz_Low_QPSK_1@0




ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:33:43

2_20MHz_Middle_QPSK_1@0



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:34:26

2_20MHz_High_QPSK_1@0



ProjectNo.:2402T74162E-RF Tester:Pedro Yun
Date: 21.MAY.2024 21:35:08