

ACOUSTMAX INTERNATIONAL CO., LTD
Unit D, 16/F, Cheuk Nang Plaza, 250 Hennessy Road
Wanchai, HongKong

Appendix to Declaration, detailed explanation

Date: October 27, 2014

Federal Communications Commission
Attn: OET Dept.
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Subject: MONSTER Tower with FCC ID: 2AAIN-BTW218

Software and operations description:

In accordance with KDB 848637 item 6, software and is implemented to ensure that proper operations modes cannot be modified by an end user or an installer. The host equipment has no software and has no instruction set to access the Radio portion for changing the RF parameters. The RF parameter modification software is only available in production and uses special coding running on a production facility, this coding is not installed, not available and therefore not accessible to any end user of this device. No hardware interface present, that end users could access in order to bypass this. Only the manufacturer is able to control and modify the software, and only in case this would be required for to meet changing FCC rules.

Software configuration attestation:

In accordance with KDB 848637 item 6, this device fully complies with the requirements for software configuration control as discussed in KDB Publication 594280 D01.

Yours Sincerely,

M. Koop
(authorized)

A handwritten signature in blue ink, appearing to read 'M. Koop', with a horizontal line extending from the end of the signature.