




FIGURE 1—TEST EQUIPMENT CONFIGURATION

Note: The coupling factor of directional coupler #2 was determined to be 56.7 dB at channel 36.