



Appendix II

Setup Photographs


RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)
CONDITION 1 MEASUREMENT POSITION




CONDITION 1 MEASUREMENT POSITION (X axis)




CONDITION 1 MEASUREMENT POSITION (Y axis)




CONDITION 1 MEASUREMENT POSITION (Z axis)




CONDITION 2 MEASUREMENT POSITION



CONDITION 2 MEASUREMENT POSITION (X axis)



CONDITION 2 MEASUREMENT POSITION (Y axis)





CONDITION 2 MEASUREMENT POSITION (Z axis)




RADIATED RF MEASUREMENT SETUP (30MHz~1GHz)




RADIATED RF MEASUREMENT SETUP (Below 30MHz)



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



RF CONDUCTION MEASUREMENT SETUP



DFS MEASUREMENT SETUP

