



20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0 -46.92 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:18:52

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0 -37.60 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:19:51

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@50 -46.17 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:20:34

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@50 -37.64 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:21:33

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB50@0 -47.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:22:11

20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB50@0 -37.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:23:08

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:24:04

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:25:02

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@50 -46.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:25:37

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@50 -37.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:26:42

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0 -46.46 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:27:15

20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0 -37.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 10:28:12

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0 -46.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:43:00

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0 -37.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:44:07

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@50 -37.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:46:10

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@50 -47.04 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:45:05

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB50@0 -37.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:48:18

20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB50@0 -46.25 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:47:12

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -37.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:05:20

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0 -46.52 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:04:23

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@105 -46.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:05:51

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@105 -37.38 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:06:47

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0 -46.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:07:17

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0 -37.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:08:14

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.21 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:10:47

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:09:50

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -46.77 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:11:20

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105 -37.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:12:17

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -37.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:13:46

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0 -46.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:12:49

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -46.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:14:21

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0 -36.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:15:19

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105 -37.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:16:50

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105 -46.79 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:15:52

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0 -46.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:17:22

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0 -37.86 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:18:19

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -37.24 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:19:55

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -46.08 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:18:58

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@132 -46.63 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:20:27

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@132 -37.60 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:21:24

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0 -47.04 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:21:56

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0 -37.72 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:22:54

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.66 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:23:30

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.09 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:24:28

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@132 -46.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:25:00

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@132 -37.63 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:25:57

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB128@0 -47.31 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:26:27

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB128@0 -37.24 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 11:27:24

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:49:21

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -37.42 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:50:27

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132 -37.39 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:52:30

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132 -47.12 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:51:24

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0 -37.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:54:34

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0 -46.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 08:53:29

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0 -47.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:00:24

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0 -38.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:01:22

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@161 -37.44 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:02:52

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@161 -45.48 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:01:55

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0 -46.51 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:03:24

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0 -36.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:04:21

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.34 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:05:55

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.93 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:04:59

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@161 -37.71 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:07:26

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@161 -47.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:06:29

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB162@0 -46.95 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:07:59

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB162@0 -37.84 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:08:56

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@0 -37.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:10:31

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@0 -46.93 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:09:33

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@161 -46.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:11:05

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@161 -37.56 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:12:03

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB162@0 -47.12 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:12:37

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB162@0 -37.02 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:13:34

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0 -47.16 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:16:05

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0 -37.29 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:17:02

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@188 -46.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:17:34

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@188 -37.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:18:31

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0 -37.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:20:02

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0 -46.03 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:19:04

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.64 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:20:38

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:21:35

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@188 -37.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:23:04

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@188 -46.70 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:22:06

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0 -46.66 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:23:36

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0 -37.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:24:34

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0 -37.44 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:26:08

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0 -47.17 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:25:11

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188 -37.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:27:38

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188 -47.21 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:26:41

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0 -37.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:29:06

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0 -46.08 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:28:09

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0 -46.31 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:29:45

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0 -37.39 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:30:42

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@216 -47.14 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:31:14

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@216 -37.92 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:32:12

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB216@0 -47.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:32:45

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB216@0 -36.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:33:42

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.74 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:35:15

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:34:17

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@216 -46.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:35:47

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@216 -37.95 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:36:44

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -45.96 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:37:17

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -37.47 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:38:14

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0 -46.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:38:50

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0 -37.78 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:39:47

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216 -47.29 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:40:20

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216 -37.41 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:41:17

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0 -37.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:42:46

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0 -47.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:41:49

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0 -45.72 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:43:26

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0 -37.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:44:24

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@244 -47.60 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:44:58

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@244 -36.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:45:57

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0 -46.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:46:35

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0 -36.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:47:34

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.33 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:49:08

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:48:11

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@244 -46.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:49:44

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@244 -36.94 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:50:42

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0 -37.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:52:16

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0 -46.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:51:17

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0 -46.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:52:52

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0 -37.21 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:53:50

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -37.24 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:55:19

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -46.35 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:54:22

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -37.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:56:50

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -47.13 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:55:53

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.44 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:58:26

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.64 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:57:29

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@272 -37.41 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:59:56

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@272 -47.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 12:58:59

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -37.62 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 13:01:26


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -46.58 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 13:00:29


n77_2

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -46.18 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:30:01

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -35.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:31:03

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@51 -46.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:31:39

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@51 -35.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:32:41

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB50@0 -35.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:34:19

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB50@0 -46.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:33:17

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.17 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:34:58

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -34.64 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:36:01

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@51 -45.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:36:37

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@51 -35.21 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:37:40

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB50@0 -34.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:39:19

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB50@0 -47.28 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:38:16

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -47.02 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:39:59

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -35.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:41:02

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@51 -46.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:41:38

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@51 -35.22 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:42:41

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB50@0 -34.99 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:44:18

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB50@0 -46.92 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:43:16


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -46.83 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng

Date: 17.MAR.2024 17:07:59


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -35.33 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng

Date: 17.MAR.2024 17:09:02


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@23 -46.39 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng

Date: 18.MAR.2024 08:56:34


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@23 -35.00 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng

Date: 18.MAR.2024 08:57:43


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0 -34.95 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng

Date: 18.MAR.2024 08:59:50


10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0 -46.76 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng


Date: 18.MAR.2024 08:58:42

10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:00:53

10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -34.96 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:02:03

10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@23 -35.10 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:04:14

10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@23 -46.74 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:03:04

10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB24@0 -34.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:06:22

10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB24@0 -47.18 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:05:13

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -46.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:07:25

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -34.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:08:36

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@23 -35.18 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:10:46

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@23 -46.74 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:09:35

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB24@0 -47.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:11:46

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB24@0 -35.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:12:55

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -34.39 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:46:02

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.47 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:44:59

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@78 -46.69 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:46:38

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@78 -35.03 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:47:40

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB75@0 -35.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:49:18

15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:48:16

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:50:13

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.46 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:51:15

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@78 -35.13 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:52:53

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@78 -46.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:51:51

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB75@0 -46.64 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:53:30

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB75@0 -35.33 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:54:31

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -35.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:56:28

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:55:27

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@78 -34.60 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:58:09

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.01 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:57:07

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:58:46

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB75@0 -34.94 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 15:59:47

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:14:00

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -33.94 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:15:09

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.17 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:16:10

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -35.48 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:17:19

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -35.26 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:19:27

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.84 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:18:18

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.45 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:20:32

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -34.71 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:21:40

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@37 -34.87 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:23:49

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@37 -45.44 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 09:22:40

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB36@0 -34.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 10:40:23

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB36@0 -45.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 10:39:19

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -35.02 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 11:11:28

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 11:10:27

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@37 -34.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 11:12:59

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 11:11:58

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 11:13:30

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB36@0 -35.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 11:14:30

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -35.03 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:01:51

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -46.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:00:49

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@105 -35.19 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:03:29

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@105 -47.08 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:02:27

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB100@0 -35.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:05:08

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB100@0 -47.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:04:07

20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -34.84 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:06:50

20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.52 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:05:48

20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -46.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:07:26

20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -34.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:08:29

20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -46.61 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:09:05

20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -35.28 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 17.MAR.2024 16:10:06