



n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@0 -47.61dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:26:40

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@77 -47.66dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:27:47

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB75@0 -42.57dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:28:55

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB100@0 -44.19dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:32:27

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@0 -47.01dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:30:11

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@105 -47.51dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:31:19

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 -47.56dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:35:56

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.17dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:33:41

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@105 -47.33dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:34:48

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB100@0 -47.13dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:39:29

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@0 -47.45dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:37:13

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@105 -47.47dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 19:38:21

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB128@0 -41.60dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 19:43:03

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@0 -46.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 19:40:46

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@132 -47.17dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 19:41:55

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 -47.34dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 19:46:35

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.54dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 19:44:20

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@132 -47.18dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 19:45:27

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB128@0 -47.70dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:50:04

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@0 -47.56dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:47:48

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@132 -47.58dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:48:56

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB162@0 -42.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 20:06:44

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@0 -47.27dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 4..JFN.2025 07:37:15

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@161 -47.55dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 4..JFN.2025 07:38:08

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 -46.12dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:10:15

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:07:58

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@161 -47.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:09:07

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB162@0 -42.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:13:45

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@0 -47.32dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:11:28

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@161 -47.63dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:12:36

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB180@0 -42.51dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 11:39:44

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@0 -47.34dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 20:15:02

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@188 -47.45dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 20:16:10

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -47.44dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:41:57

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.39dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:40:10

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -47.50dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:41:03

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -43.38dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:44:47

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -47.81dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:43:01

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -47.33dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:43:54

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -47.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 20:54:33

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -47.41dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 20:55:42

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -40.12dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:45:49

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -46.89dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:58:08

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -47.67dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 20:59:19

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -46.16dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 21:00:28

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -46.82dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 21:01:45

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.43dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 21:02:56

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -46.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 21:04:07

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -47.05dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:05:25

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -46.84dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:06:35

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -41.83dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:07:46

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.71dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:09:05

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -45dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:10:16

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -43.05dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:11:28

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -47.57dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:12:43

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -45.14dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:13:53

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -47.07dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:15:03

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -47.51dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:16:22

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -43.96dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:17:32

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -44.44dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 11:56:59

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -46.92dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:19:59

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -43.89dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:21:10

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -42.51dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:22:21

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -47.06dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:23:37

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -44.35dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:24:48

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -45.61dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:25:59