



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 12.MAR.2022 16:32:22

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 12.MAR.2022 10:38:25

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 12.MAR.2022 10:38:48

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 12.MAR.2022 10:39:10

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 12.MAR.2022 10:39:33

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 12.MAR.2022 10:39:48

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 12.MAR.2022 10:40:08

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 12.MAR.2022 10:40:27

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 12.MAR.2022 10:40:46

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 12.MAR.2022 10:41:05

Band 2_3 MHz_High_QPSK_RB15#0




Date: 12.MAR.2022 10:41:21

Band 2_3 MHz_High_16QAM_RB15#0




Date: 12.MAR.2022 10:41:36

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 10:41:58

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 10:42:15

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 12.MAR.2022 10:42:34

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 12.MAR.2022 10:42:54

Band 2_5 MHz_High_QPSK_RB25#0




Date: 12.MAR.2022 10:43:15

Band 2_5 MHz_High_16QAM_RB25#0




Date: 12.MAR.2022 10:43:36

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 10:44:06

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 10:44:31

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 12.MAR.2022 10:44:56

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 12.MAR.2022 10:45:22

Band 2_10 MHz_High_QPSK_RB50#0




Date: 12.MAR.2022 10:45:53

Band 2_10 MHz_High_16QAM_RB50#0




Date: 12.MAR.2022 10:46:24

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 10:46:56

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 10:47:20

Band 2 15 MHz Middle QPSK RB75#0




Date: 12.MAR.2022 10:47:54

Band 2 15 MHz Middle 16QAM RB75#0




Date: 12.MAR.2022 10:48:28

Band 2_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 10:48:58

Band 2_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 10:49:26

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 10:49:57

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 10:50:28

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 12.MAR.2022 10:50:59

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 12.MAR.2022 10:51:29

Band 2_20 MHz_High_QPSK_RB100#0




Date: 12.MAR.2022 10:52:00

Band 2_20 MHz_High_16QAM_RB100#0




Date: 12.MAR.2022 10:52:34

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 12.MAR.2022 10:52:49

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 12.MAR.2022 10:53:04

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 12.MAR.2022 10:53:22

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 12.MAR.2022 10:53:37

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 12.MAR.2022 10:53:55

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 12.MAR.2022 10:54:10

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 12.MAR.2022 10:54:32

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 12.MAR.2022 10:54:47

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 12.MAR.2022 10:55:08

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 12.MAR.2022 10:55:26

Band 4_3 MHz_High_QPSK_RB15#0



Date: 12.MAR.2022 10:55:44

Band 4_3 MHz_High_16QAM_RB15#0



Date: 12.MAR.2022 10:55:59