







Band 38_10 MHz_High_QPSK_RB50#0




Date: 12.MAR.2022 15:00:41

Band 38_10 MHz_High_16QAM_RB50#0




Date: 12.MAR.2022 15:01:09

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 15:01:34

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 15:01:57

Band 38_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 15:02:24

Band 38_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 15:02:54

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 15:03:19

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 15:03:49


Band 38_20 MHz_High_QPSK_RB100#0



Band 38_20 MHz_High_16QAM_RB100#0




Band 41_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 15:47:56

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 15:48:10


Band 41_5 MHz_High_QPSK_RB25#0



Band 41_5 MHz_High_16QAM_RB25#0




Band 41_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 15:48:54

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 15:49:12

Band 41_10 MHz_High_QPSK_RB50#0




Date: 12.MAR.2022 15:49:34

Band 41_10 MHz_High_16QAM_RB50#0




Date: 12.MAR.2022 15:49:59

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 15:50:17

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 15:50:37

Band 41_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 15:51:01

Band 41_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 15:51:22

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 15:51:50

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 15:52:17


Band 41_20 MHz_High_QPSK_RB100#0



Band 41_20 MHz_High_16QAM_RB100#0




Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 12.MAR.2022 12:19:56

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 12.MAR.2022 12:20:13

Band 66_1.4 MHz_High_QPSK_RB6#0





Date: 12.MAR.2022 12:20:28


Band 66_1.4 MHz_High_16QAM_RB6#0



Date: 12.MAR.2022 12:20:39




Band 66_3 MHz_High_QPSK_RB15#0




Date: 12.MAR.2022 12:21:32

Band 66_3 MHz_High_16QAM_RB15#0




Date: 12.MAR.2022 12:21:52

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 12:22:07

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 12:22:27


Band 66_5 MHz_High_QPSK_RB25#0



Band 66_5 MHz_High_16QAM_RB25#0




Band 66_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 12:23:25

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 12:23:46


Band 66_10 MHz_High_QPSK_RB50#0



Band 66_10 MHz_High_16QAM_RB50#0




Band 66_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 12:25:04

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 12:25:24

Band 66_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 12:25:45

Band 66_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 12:26:21

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 12:27:02

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 12:27:35

Band 66_20 MHz_High_QPSK_RB100#0



Date: 12.MAR.2022 12:27:59

Band 66_20 MHz_High_16QAM_RB100#0



Date: 12.MAR.2022 12:28:32