




n78_2_50MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB133@0 47.424MHz




n78_2_50MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB133@0 47.480MHz




n78_2_50MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB133@0 47.286MHz



n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0 57.879MHz




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 57.707MHz




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB162@0 57.661MHz



n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB162@0 57.904MHz




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB162@0 57.466MHz



n78_2_60MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB162@0 57.656MHz



n78_2_60MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB162@0 57.673MHz



n78_2_60MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB162@0 57.680MHz




n78_2_60MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB162@0 57.661MHz




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB180@0 66.965MHz




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 66.612MHz



n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB180@0 66.312MHz



n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB180@0 66.564MHz




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB180@0 66.298MHz




n78_2_70MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB189@0 67.326MHz




n78_2_70MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB189@0 67.323MHz




n78_2_70MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB189@0 67.231MHz



n78_2_70MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB189@0 67.293MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0 77.245MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 76.916MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB216@0 76.900MHz



n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB216@0 76.951MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB216@0 76.928MHz



n78_2_80MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB217@0 77.245MHz




n78_2_80MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB217@0 77.180MHz



n78_2_80MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB217@0 77.245MHz




n78_2_80MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB217@0 77.448MHz




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0 86.504MHz




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 86.768MHz




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB243@0 86.514MHz



n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB243@0 86.814MHz



n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB243@0 86.767MHz



n78_2_90MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB245@0 87.159MHz

