




n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB216@0 77.135MHz




n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB216@0 76.933MHz



n78_3_80MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB217@0 77.243MHz




n78_3_80MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB217@0 77.162MHz




n78_3_80MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB217@0 77.222MHz




n78_3_80MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB217@0 77.261MHz




n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0 86.432MHz




n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB243@0 86.442MHz



n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB243@0 86.474MHz



n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB243@0 86.571MHz




n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB243@0 86.538MHz




n78_3_90MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB245@0 87.158MHz



n78_3_90MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB245@0 87.175MHz




n78_3_90MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB245@0 87.195MHz



n78_3_90MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB245@0 87.167MHz



n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB270@0 96.425MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 96.064MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB270@0 96.546MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB270@0 96.412MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB270@0 96.078MHz




n78_3_100MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB273@0 97.238MHz



n78_3_100MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB273@0 96.975MHz



n78_3_100MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB273@0 97.224MHz



n78_3_100MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB273@0 96.939MHz

