



n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -36.32dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:00:47

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@132 -36.24dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:01:43

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB128@0 -36.70dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:05:41

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@0 -36.67dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:03:47

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@132 -36.73dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:04:44

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -36.82dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:08:40

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -36.54dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:06:45

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@161 -36.11dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:07:42

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB162@0 -36.53dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:12:38

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -36.30dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:10:44

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@161 -36.72dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:11:41

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB162@0 -35.73dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:15:37

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@0 -36.38dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:13:42

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@161 -36.54dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:14:40

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -36.73dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:18:38

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -36.50dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:16:42

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@188 -36.96dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:17:40

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB180@0 -36.62dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:21:36

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -36.50dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 24.SEP.2024 02:19:41

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@188 -36.55dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 24.SEP.2024 02:20:38

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB180@0 -36.09dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 24.SEP.2024 02:24:34

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@0 -36.76dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 24.SEP.2024 02:22:39

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@188 -36.51dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 24.SEP.2024 02:23:37

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -36.33dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 24.SEP.2024 02:25:40

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@216 -36.50dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:26:35

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -36.35dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:27:36

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -36.80dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:36:02

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@216 -36.88dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:36:59

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB216@0 -36.55dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:37:57

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@0 -36.79dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 02:38:59

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@216 -36.87dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:39:56

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB216@0 -36.11dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:40:53

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -35.70dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:41:56

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@244 -36.47dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:42:57

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -36.21dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:43:54

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -36.18dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:44:57

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@244 -35.73dBm




ProjectNo.: 2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 02:45:55

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB243@0 -36.44dBm




ProjectNo.: 2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 02:46:53

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@0 -36.65dBm




ProjectNo.: 2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 02:47:56

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244 -37.10dBm




ProjectNo.: 2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 02:48:54

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0 -36.97dBm




ProjectNo.: 2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 02:49:52

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.59dBm




ProjectNo.: 2401W26164E-RF Tester:Kungfumeister Liang
Date: 24.SEP.2024 02:50:59

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -37.04dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:51:56

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -36.86dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:52:59

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -36.31dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:54:03

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@272 -35.41dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:55:03

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB270@0 -36.80dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:56:03

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@0 -36.54dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 02:57:07

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272 -36.20dBm



ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 24.SEP.2024 02:58:07


n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0 -36.47dBm



ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 24.SEP.2024 02:59:07


n78_1

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -40.34dBm




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 24.SEP.2024 04:03:08

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -40.55dBm




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 24.SEP.2024 01:04:05

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -40.81dBm




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 24.SEP.2024 04:05:02

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.81dBm




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 24.SEP.2024 01:06:04


n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -40.35dBm




n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -40.97dBm




n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -40.98dBm




n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -40.96dBm




n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -40.85dBm



n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -40.25dBm




n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -40.61dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:12:57

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -40.59dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:13:55

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.69dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:14:56

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -41.03dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:15:57

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -40.46dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:16:56

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -40.35dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:18:00

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -40.68dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:19:00

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -40.87dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:19:59

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -40.93dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:21:07

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -40.92dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:22:07

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -40.47dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:23:06

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.41dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 24.SEP.2024 04:24:40