




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB38@0 13.575MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB38@0 13.569MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB38@0 13.589MHz




n41\_15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.448MHz






n41\_15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.447MHz




n41\_15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.517MHz




n41\_15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM 256  
QAM RB36@0 13.453MHz

n41\_15MHz\_30kHz\_2682.48MHz\_CP-OFDM 16  
QAM RB38@0 13.562MHzn41\_15MHz\_30kHz\_2682.48MHz\_CP-OFDM 256  
OAM RB38@0 13.571MHz


n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.033MHz




n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.023MHz



n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.095MHz




n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.030MHz




n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.080MHz




n41\_20MHz\_30kHz\_2506.02MHz\_CP-OFDM  
QPSK\_RB51@0 18.170MHz




n41\_20MHz\_30kHz\_2506.02MHz\_CP-OFDM 16  
QAM\_RB51@0 18.178MHz




n41\_20MHz\_30kHz\_2506.02MHz\_CP-OFDM 64  
QAM\_RB51@0 18.186MHz




n41\_20MHz\_30kHz\_2506.02MHz\_CP-OFDM 256  
QAM\_RB51@0 18.190MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.032MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.025MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.029MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.029MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.029MHz



n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB51@0 18.176MHz




n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB51@0 18.167MHz




n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB51@0 18.179MHz




n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB51@0 18.185MHz



n41\_20MHz\_30kHz\_2679.99MHz\_DFT-s-OFDM  
QPSK RB50@0 18.100MHz



n41\_20MHz\_30kHz\_2679.99MHz\_DFT-s-OFDM 64  
QAM RB50@0 18.033MHz

n41\_20MHz\_30kHz\_2679.99MHz\_CP-OFDM  
OPSK RB51@0 18.183MHz