






n41\_30MHz\_30kHz\_2511MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.740MHz




n41\_30MHz\_30kHz\_2511MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.536MHz




n41\_30MHz\_30kHz\_2511MHz\_CP-OFDM QPSK\_RB78@0  
27.865MHz




n41\_30MHz\_30kHz\_2511MHz\_CP-OFDM 16  
QAM\_RB78@0 27.775MHz




n41\_30MHz\_30kHz\_2511MHz\_CP-OFDM 64  
QAM\_RB78@0 27.772MHz




n41\_30MHz\_30kHz\_2511MHz\_CP-OFDM 256  
QAM\_RB78@0 27.775MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.501MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.506MHz



n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.729MHz



n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.609MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.505MHz




n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB78@0 27.857MHz




n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB78@0 27.773MHz




n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB78@0 27.763MHz




n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB78@0 27.766MHz



n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.617MHz




n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.652MHz




n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.778MHz




n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.744MHz




n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.637MHz




n41\_30MHz\_30kHz\_2674.98MHz\_CP-OFDM  
QPSK\_RB78@0 27.873MHz




n41\_30MHz\_30kHz\_2674.98MHz\_CP-OFDM 16  
QAM\_RB78@0 27.883MHz




n41\_30MHz\_30kHz\_2674.98MHz\_CP-OFDM 64  
QAM\_RB78@0 27.770MHz




n41\_30MHz\_30kHz\_2674.98MHz\_CP-OFDM 256  
QAM\_RB78@0 27.849MHz




n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.465MHz




n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.484MHz



n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.286MHz



n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.198MHz



n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.292MHz



n41\_40MHz\_30kHz\_2516.01MHz\_CP-OFDM  
QPSK\_RB106@0 37.767MHz

