




n41_50MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM RB133@0 47.426MHz




n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM $\pi/2$
BPSK RB128@0 47.297MHz

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM 16
OAM RB128@0 47.231MHz


n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM 64
QAM_RB128@0 47.038MHz




n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM 256
QAM_RB128@0 47.410MHz



n41_50MHz_30kHz_2664.99MHz_CP-OFDM
QPSK_RB133@0 47.459MHz



n41_50MHz_30kHz_2664.99MHz_CP-OFDM 16
QAM_RB133@0 47.466MHz




n41_50MHz_30kHz_2664.99MHz_CP-OFDM 64
QAM_RB133@0 47.454MHz




n41_50MHz_30kHz_2664.99MHz_CP-OFDM 256
QAM_RB133@0 47.416MHz




n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK RB162@0 57.857MHz

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM 64
OAM RB162@0 57.956MHz


n41_60MHz_30kHz_2526MHz_CP-OFDM
OPSK_RB162@0_57.685MHz




n41_60MHz_30kHz_2526MHz_CP-OFDM 16
QAM_RB162@0 57.697MHz




n41_60MHz_30kHz_2526MHz_CP-OFDM 64
QAM_RB162@0 57.850MHz



n41_60MHz_30kHz_2526MHz_CP-OFDM 256
QAM_RB162@0 57.878MHz



n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0 57.702MHz




n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0 57.608MHz




n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB162@0 57.477MHz




n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB162@0 57.887MHz




n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB162@0 57.473MHz



n41_60MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB162@0 57.682MHz



n41_60MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB162@0 57.667MHz




n41_60MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB162@0 57.708MHz



n41_60MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB162@0 57.627MHz



n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK RB162@0 57.848MHz

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM 64
QAM RB162@0 57.925MHzn41_60MHz_30kHz_2659.98MHz_CP-OFDM
QPSK RB162@0 57.693MHz