




n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.081MHz




n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 18.026MHz



n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB50@0 18.093MHz



n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB50@0 18.026MHz




n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB50@0 18.017MHz




n77_1_20MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB51@0 18.170MHz




n77_1_20MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB51@0 18.183MHz




n77_1_20MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB51@0 18.166MHz



n77_1_20MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB51@0 18.183MHz




n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.017MHz




n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 18.087MHz




n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM 16
QAM_RB50@0 18.099MHz



n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM 64
QAM_RB50@0 18.090MHz




n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM 256
QAM_RB50@0 18.009MHz




n77_1_20MHz_30kHz_3540MHz_CP-OFDM
QPSK_RB51@0 18.176MHz




n77_1_20MHz_30kHz_3540MHz_CP-OFDM 16
QAM_RB51@0 18.180MHz




n77_1_20MHz_30kHz_3540MHz_CP-OFDM 64
QAM_RB51@0 18.176MHz




n77_1_20MHz_30kHz_3540MHz_CP-OFDM 256
QAM_RB51@0 18.183MHz




n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.539MHz




n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 27.602MHz




n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM 16
QAM_RB75@0 27.745MHz



n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM 64
QAM_RB75@0 27.740MHz




n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM 256
QAM_RB75@0 27.507MHz




n77_1_30MHz_30kHz_3465MHz_CP-OFDM
QPSK_RB78@0 27.856MHz




n77_1_30MHz_30kHz_3465MHz_CP-OFDM 16
QAM_RB78@0 27.768MHz




n77_1_30MHz_30kHz_3465MHz_CP-OFDM 64
QAM_RB78@0 27.775MHz



n77_1_30MHz_30kHz_3465MHz_CP-OFDM 256
QAM_RB78@0 27.750MHz




n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.621MHz




n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 27.644MHz




n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB75@0 27.751MHz




n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB75@0 27.749MHz




n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB75@0 27.537MHz




n77_1_30MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB78@0 27.853MHz



n77_1_30MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB78@0 27.851MHz



n77_1_30MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB78@0 27.776MHz



n77_1_30MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB78@0 27.764MHz

