



n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.012MHz




n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM 16
QAM_RB50@0 18.030MHz




n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM 256
QAM_RB50@0 18.037MHz




n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB50@0 18.085MHz




n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM 64
QAM_RB50@0 18.023MHz




n77_3_20MHz_30kHz_3970MHz_CP-OFDM
QPSK_RB51@0 18.180MHz



n77_3_20MHz_30kHz_3970MHz_CP-OFDM 16
QAM_RB51@0 18.178MHz




n77_3_20MHz_30kHz_3970MHz_CP-OFDM 64
QAM_RB51@0 18.192MHz




n77_3_20MHz_30kHz_3970MHz_CP-OFDM 256
QAM_RB51@0 18.189MHz




n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.606MHz




n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 27.610MHz




n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM 16
QAM_RB75@0 27.745MHz




n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM 64
QAM_RB75@0 27.612MHz




n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM 256
QAM_RB75@0 27.493MHz




n77_3_30MHz_30kHz_3715MHz_CP-OFDM
QPSK_RB78@0 27.859MHz




n77_3_30MHz_30kHz_3715MHz_CP-OFDM 16
QAM_RB78@0 27.771MHz




n77_3_30MHz_30kHz_3715MHz_CP-OFDM 64
QAM_RB78@0 27.755MHz




n77_3_30MHz_30kHz_3715MHz_CP-OFDM 256
QAM_RB78@0 27.765MHz




n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.623MHz




n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB75@0 27.628MHz




n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB75@0 27.733MHz




n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB75@0 27.613MHz




n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB75@0 27.497MHz




n77_3_30MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB78@0 27.877MHz




n77_3_30MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB78@0 27.771MHz




n77_3_30MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB78@0 27.752MHz



n77_3_30MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB78@0 27.757MHz




n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.605MHz




n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB75@0 27.607MHz




n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM 16
QAM_RB75@0 27.737MHz




n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM 64
QAM_RB75@0 27.605MHz




n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM 256
QAM_RB75@0 27.502MHz




n77_3_30MHz_30kHz_3965MHz_CP-OFDM
QPSK_RB78@0 27.853MHz



n77_3_30MHz_30kHz_3965MHz_CP-OFDM 16
QAM_RB78@0 27.874MHz



n77_3_30MHz_30kHz_3965MHz_CP-OFDM 64
QAM_RB78@0 27.758MHz



n77_3_30MHz_30kHz_3965MHz_CP-OFDM 256
QAM_RB78@0 27.842MHz

