




n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM 64
QAM_RB50@0 18.088MHz




n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM 256
QAM_RB50@0 18.005MHz




n78_1_20MHz_30kHz_3540MHz_CP-OFDM
QPSK_RB51@0 18.177MHz



n78_1_20MHz_30kHz_3540MHz_CP-OFDM 16
QAM_RB51@0 18.168MHz




n78_1_20MHz_30kHz_3540MHz_CP-OFDM 64
QAM_RB51@0 18.179MHz




n78_1_20MHz_30kHz_3540MHz_CP-OFDM 256
QAM_RB51@0 18.184MHz




n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.605MHz




n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 27.631MHz




n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM 16
QAM_RB75@0 27.745MHz




n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM 64
QAM_RB75@0 27.726MHz




n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM 256
QAM_RB75@0 27.502MHz




n78_1_30MHz_30kHz_3465MHz_CP-OFDM
QPSK_RB78@0 27.864MHz




n78_1_30MHz_30kHz_3465MHz_CP-OFDM 16
QAM_RB78@0 27.768MHz




n78_1_30MHz_30kHz_3465MHz_CP-OFDM 64
QAM_RB78@0 27.840MHz



n78_1_30MHz_30kHz_3465MHz_CP-OFDM 256
QAM_RB78@0 27.750MHz




n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.627MHz




n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 27.612MHz




n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB75@0 27.747MHz




n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB75@0 27.649MHz




n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB75@0 27.524MHz




n78_1_30MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB78@0 27.873MHz




n78_1_30MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB78@0 27.771MHz




n78_1_30MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB78@0 27.776MHz




n78_1_30MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB78@0 27.760MHz




n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.630MHz




n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 27.606MHz



n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM 16
QAM_RB75@0 27.746MHz



n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM 64
QAM_RB75@0 27.651MHz




n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM 256
QAM_RB75@0 27.522MHz




n78_1_30MHz_30kHz_3535MHz_CP-OFDM
QPSK_RB78@0 27.856MHz




n78_1_30MHz_30kHz_3535MHz_CP-OFDM 16
QAM_RB78@0 27.860MHz




n78_1_30MHz_30kHz_3535MHz_CP-OFDM 64
QAM_RB78@0 27.756MHz



n78_1_30MHz_30kHz_3535MHz_CP-OFDM 256
QAM_RB78@0 27.771MHz



n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.604MHz



n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 37.506MHz



n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM 16
QAM_RB100@0 37.199MHz

