



n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM RB128@0 46.874MHz





n78_1_50MHz_30kHz_3500MHz_CP-OFDM 16
QAM RB133@0 47.402MHz




n78_1_50MHz_30kHz_3500MHz_CP-OFDM 256
QAM RB133@0 47.276MHz




n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK RB128@0 46.840MHz

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM 64
OAM RB128@0 46.852MHz


n78_1_50MHz_30kHz_3525MHz_CP-OFDM
QPSK RB133@0 47.420MHz




n78_1_50MHz_30kHz_3525MHz_CP-OFDM 64
QAM RB133@0 47.415MHz




n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM $\pi/2$
BPSK RB162@0 57.684MHz

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM 16
QAM RB162@0 57.470MHz


n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM 64
QAM_RB162@0 57.888MHz




n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM 256
QAM_RB162@0 57.680MHz



n78_1_60MHz_30kHz_3480MHz_CP-OFDM
QPSK_RB162@0 57.654MHz



n78_1_60MHz_30kHz_3480MHz_CP-OFDM 16
QAM_RB162@0 57.650MHz




n78_1_60MHz_30kHz_3480MHz_CP-OFDM 64
QAM_RB162@0 57.717MHz



n78_1_60MHz_30kHz_3480MHz_CP-OFDM 256
QAM_RB162@0 57.609MHz




n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK RB162@0 57.694MHz

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM 64
OAM RB162@0 57.900MHz


n78_1_60MHz_30kHz_3500MHz_CP-OFDM
OPSK RB162@0 57.629MHz




n78_1_60MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB162@0 57.660MHz




n78_1_60MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB162@0 57.708MHz




n78_1_60MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB162@0 57.469MHz



n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0 57.695MHz



n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 57.702MHz



n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM 16
QAM_RB162@0 57.699MHz

