




n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM 64
QAM_RB75@0 27.641MHz




n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM 256
QAM_RB75@0 27.512MHz




n78_3_30MHz_30kHz_3715MHz_CP-OFDM
QPSK_RB78@0 27.852MHz




n78_3_30MHz_30kHz_3715MHz_CP-OFDM 16
QAM_RB78@0 27.762MHz




n78_3_30MHz_30kHz_3715MHz_CP-OFDM 64
QAM_RB78@0 27.747MHz




n78_3_30MHz_30kHz_3715MHz_CP-OFDM 256
QAM_RB78@0 27.740MHz




n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.615MHz




n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB75@0 27.605MHz



n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB75@0 27.729MHz



n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB75@0 27.622MHz




n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB75@0 27.503MHz




n78_3_30MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB78@0 27.845MHz




n78_3_30MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB78@0 27.771MHz




n78_3_30MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB78@0 27.743MHz



n78_3_30MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB78@0 27.760MHz




n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.618MHz




n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0 27.605MHz




n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM 16
QAM_RB75@0 27.746MHz




n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM 64
QAM_RB75@0 27.745MHz




n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM 256
QAM_RB75@0 27.526MHz




n78_3_30MHz_30kHz_3785MHz_CP-OFDM
QPSK_RB78@0 27.866MHz




n78_3_30MHz_30kHz_3785MHz_CP-OFDM 16
QAM_RB78@0 27.868MHz




n78_3_30MHz_30kHz_3785MHz_CP-OFDM 64
QAM_RB78@0 27.775MHz




n78_3_30MHz_30kHz_3785MHz_CP-OFDM 256
QAM_RB78@0 27.763MHz




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.461MHz




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 37.497MHz




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM 16
QAM_RB100@0 37.285MHz



n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM 64
QAM_RB100@0 37.187MHz




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM 256
QAM_RB100@0 37.291MHz




n78_3_40MHz_30kHz_3720MHz_CP-OFDM
QPSK_RB106@0 37.801MHz




n78_3_40MHz_30kHz_3720MHz_CP-OFDM 16
QAM_RB106@0 37.792MHz




n78_3_40MHz_30kHz_3720MHz_CP-OFDM 64
QAM_RB106@0 37.822MHz




n78_3_40MHz_30kHz_3720MHz_CP-OFDM 256
QAM_RB106@0 37.781MHz



n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.472MHz



n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB100@0 37.520MHz



n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB100@0 37.286MHz

