



n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM 64
QAM_RB180@0 66.566MHz




n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM 256
QAM_RB180@0 66.334MHz



n78_3_70MHz_30kHz_3735MHz_CP-OFDM
QPSK_RB189@0 67.322MHz



n78_3_70MHz_30kHz_3735MHz_CP-OFDM 16
QAM_RB189@0 67.537MHz



n78_3_70MHz_30kHz_3735MHz_CP-OFDM 64
QAM_RB189@0 67.333MHz



n78_3_70MHz_30kHz_3735MHz_CP-OFDM 256
QAM_RB189@0 67.311MHz



Transceiver A

NEW! F44 B2 (11/3)
Unsaved HW

KEYSIGHT

Input: HP101
Output: HP101
Coupler: A1

Corr: User

Range: -60 dBm

Imp: 170 Ohm
Align: Off
Gate: OFF

Carrier Freq: 3.75000000 GHz
CW type: Unmod, 1 CW

SW: **PASS**

5 MHz

Scale/DW: 10.0 dB

Ref Min: 40.00 dBm

Center: 3.75000 GHz
Span: 400 MHz

#VIDW: DW 3.0000 MHz

Span: 160 MHz
Sweep: 1.000 sec, 0.0001 GHz


5 Minutes

Unziped Histogram		Action Threshold	
66.7 ± 2 MHz		Total Power	30.0 dBm
Transmit Freq Error	0 Hz	% of ODW Power	99.00 %
x dB Bandwidth	65.64 MHz	x dB	-26.00 dB


Sep 28, 2024 10:07:25 AM

[illegible][illegible][illegible][illegible][illegible]


n78_3_70MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB189@0 67.530MHz




n78_3_70MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB189@0 67.248MHz



n78_3_70MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB189@0 67.287MHz



n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM $\pi/2$
BPSK_RB180@0 66.903MHz




n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0 66.692MHz




n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM 16
QAM_RB180@0 66.374MHz




n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM 256
QAM RB180@0 66.257MHz

n78_3_70MHz_30kHz_3765MHz_CP-OFDM 16
OAM RB189@0 67.346MHzn78_3_70MHz_30kHz_3765MHz_CP-OFDM 256
OAM RB189@0 67.318MHz


n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0 77.134MHz




n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 76.914MHz




n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM 16
QAM_RB216@0 76.933MHz




n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM 64
QAM_RB216@0 76.944MHz




n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM 256
QAM_RB216@0 76.825MHz




n78_3_80MHz_30kHz_3740MHz_CP-OFDM
QPSK_RB217@0 77.457MHz




n78_3_80MHz_30kHz_3740MHz_CP-OFDM 16
QAM_RB217@0 77.177MHz




n78_3_80MHz_30kHz_3740MHz_CP-OFDM 64
QAM_RB217@0 77.448MHz




n78_3_80MHz_30kHz_3740MHz_CP-OFDM 256
QAM_RB217@0 77.272MHz



n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0 77.221MHz



n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB216@0 76.847MHz



n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB216@0 76.856MHz

