




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB50@0 18.028MHz



n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB50@0 18.017MHz



n77_2_20MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB51@0 18.119MHz



n77_2_20MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB51@0 18.188MHz




n77_2_20MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB51@0 18.170MHz




n77_2_20MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB51@0 18.186MHz



n77_2_20MHz_30kHz_3690MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.015MHz




n77_2_20MHz_30kHz_3690MHz_DFT-s-OFDM 16
QAM_RB50@0 18.027MHz



n77_2_20MHz_30kHz_3690MHz_DFT-s-OFDM 256
QAM_RB50@0 18.084MHz



n77_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB50@0 18.026MHz



n77_2_20MHz_30kHz_3690MHz_DFT-s-OFDM 64
QAM_RB50@0 18.027MHz




n77_2_20MHz_30kHz_3690MHz_CP-OFDM
QPSK_RB51@0 18.242MHz




n77_2_20MHz_30kHz_3690MHz_CP-OFDM 16
QAM_RB51@0 18.183MHz




n77_2_20MHz_30kHz_3690MHz_CP-OFDM 64
QAM_RB51@0 18.180MHz




n77_2_20MHz_30kHz_3690MHz_CP-OFDM 256
QAM_RB51@0 18.192MHz




n77_2_30MHz_30kHz_3565MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.607MHz




n77_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB75@0 27.622MHz




n77_2_30MHz_30kHz_3565MHz_DFT-s-OFDM 16
QAM_RB75@0 27.748MHz




n77_2_30MHz_30kHz_3565MHz_DFT-s-OFDM 64
QAM_RB75@0 27.629MHz




n77_2_30MHz_30kHz_3565MHz_DFT-s-OFDM 256
QAM_RB75@0 27.523MHz



n77_2_30MHz_30kHz_3565MHz_CP-OFDM
QPSK_RB78@0 27.851MHz



n77_2_30MHz_30kHz_3565MHz_CP-OFDM 16
QAM_RB78@0 27.773MHz



n77_2_30MHz_30kHz_3565MHz_CP-OFDM 64
QAM_RB78@0 27.762MHz




n77_2_30MHz_30kHz_3565MHz_CP-OFDM 256
QAM_RB78@0 27.769MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.635MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 27.608MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB75@0 27.748MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB75@0 27.733MHz



n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB75@0 27.520MHz



n77_2_30MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB78@0 27.855MHz



n77_2_30MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB78@0 27.863MHz




n77_2_30MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB78@0 27.772MHz



n77_2_30MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB78@0 27.754MHz



n77_2_30MHz_30kHz_3685MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.621MHz



n77_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB75@0 27.618MHz



n77_2_30MHz_30kHz_3685MHz_DFT-s-OFDM 16
QAM_RB75@0 27.741MHz

