



n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -26.526MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 23_SEP.2024 17:44:42

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB162@0 -42.690MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 23_SEP.2024 17:47:14

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@161 -29.164MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 23_SEP.2024 17:46:24

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -43.864MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 23_SEP.2024 17:49:09

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -34.135MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 23_SEP.2024 17:48:18

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB180@0 -42.792MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfumeister Liang
Date: 23_SEP.2024 17:50:56

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@188 -33.450MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:50:05

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -24.207MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:52:16

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -28.538MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:53:06

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@216 -25.589MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:54:32

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB216@0 -38.435MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:55:23

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -23.183MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:56:43

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -26.395MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:57:33

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244 -24.305MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:59:01

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0 -42.591MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 17:59:53

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -23.391MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:01:15

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -26.582MHz



ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:02:06


n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272 -22.913MHz



ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:06:26


n78_1

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0 -42.653MHz




ProjectNo.:2401W26164E-RF Testset:Kungfumeister Liang
Date: 23_SEP.2024 18:07:15

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -32.049MHz




ProjectNo.:2401W26164E-RF Testset:Kungfumeister Liang
Date: 23_SEP.2024 19:19:13

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -35.928MHz




ProjectNo.:2401W26164E-RF Testset:Kungfumeister Liang
Date: 23_SEP.2024 18:20:13

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -33.888MHz




ProjectNo.:2401W26164E-RF Testset:Kungfumeister Liang
Date: 23_SEP.2024 19:21:18

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -42.929MHz




ProjectNo.:2401W26164E-RF Testset:Kungfumeister Liang
Date: 23_SEP.2024 18:22:17

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -31.381MHz




ProjectNo.:2401W26164E-RF Testset:Kungfumeister Liang
Date: 23_SEP.2024 19:23:25

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -41.859MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:24:26

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -33.273MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:25:28

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -44.048MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:26:26

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -38.212MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:27:35

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -43.940MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:28:36

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -37.402MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:29:39

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -43.820MHz




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 23.SEP.2024 18:30:38

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -34.503MHz




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 23.SEP.2024 18:36:06

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -43.665MHz




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 23.SEP.2024 18:37:10

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -35.208MHz




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 23.SEP.2024 18:38:17

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -43.900MHz




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 23.SEP.2024 18:39:18

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -41.039MHz




ProjectNo.: 2401W26164E-RF Tester: Kungfumeister Liang
Date: 23.SEP.2024 18:41:32

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -25.086MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 18:40:25

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -44.097MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 18:43:39

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -26.645MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 18:42:38

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -43.927MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 18:45:44

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -31.220MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 18:44:48

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -44.239MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 18:47:43

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -31.653MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:46:47

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -43.941MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:49:47

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -26.265MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:48:45

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -44.144MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:51:59

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -27.912MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:50:57

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -44.059MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:54:10

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -35.231MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:53:08

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -43.820MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:56:13

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -35.394MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:55:15

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -26.795MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 19:23:26

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -28.544MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 18:58:18

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -27.225MHz




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 23_SEP.2024 19:31:52

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -40.024MHz




ProjectNo.: 2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 19:00:20

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -23.536MHz




ProjectNo.: 2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 19:26:07

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -27.839MHz




ProjectNo.: 2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 19:02:24

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -26.528MHz




ProjectNo.: 2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 19:27:34

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -45.899MHz




ProjectNo.: 2401W26164E-RF Tester:Kungfumaster Liang
Date: 9.OCT.2024 17:38:14

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -24.152MHz




ProjectNo.: 2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 19:09:05

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -40.539MHz




ProjectNo.:2401W26164E-RF Testers:Kungfumeister Liang
Date: 8.OCT.2024 17:40:10

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -36.074MHz




ProjectNo.:2401W26164E-RF Testers:Kungfumeister Liang
Date: 23.SEP.2024 19:29:01

n78_3
n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -34.021MHz




ProjectNo.:2401W26164E-RF Testers:Kungfumeister Liang
Date: 23.SEP.2024 20:45:54

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -33.154MHz




ProjectNo.:2401W26164E-RF Testers:Kungfumeister Liang
Date: 23.SEP.2024 20:46:32

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@23 -33.112MHz




ProjectNo.:2401W26164E-RF Testers:Kungfumeister Liang
Date: 23.SEP.2024 20:47:16

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB24@0 -42.901MHz




ProjectNo.:2401W26164E-RF Testers:Kungfumeister Liang
Date: 23.SEP.2024 20:47:54

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -29.759MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:03:35

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -42.758MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:04:14

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37 -32.634MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:04:56

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0 -43.292MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:05:38

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -37.600MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:12:21

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -43.601MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:13:01

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@50 -38.092MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:13:47

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB50@0 -43.155MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:14:28

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -34.177MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:48:50

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -43.731MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:49:32

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@77 -32.986MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:50:21

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0 -42.978MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:51:04

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -40.721MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:55:27

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -24.058MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:54:42

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0 -43.117MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:57:04

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105 -24.891MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:56:18

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -43.715MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:59:32

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -31.774MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 21:58:46

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0 -43.073MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:01:12

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132 -32.146MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:00:24

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -43.752MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:03:37

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -26.551MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:02:53

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0 -43.184MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:05:18

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161 -27.410MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:04:33

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -43.802MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:07:43

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -33.470MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:06:59

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0 -43.286MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:09:24

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@188 -33.915MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:08:39

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -24.896MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:11:37

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -30.062MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:12:22

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216 -23.037MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:13:36

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0 -38.800MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:14:23

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -26.049MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:16:27

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -29.639MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:17:13

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244 -26.803MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:18:27

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0 -42.924MHz




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 23_SEP.2024 22:19:13

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -21.709MHz




ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 22:27:32

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -39.618MHz



ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 8.OCT.2024 17:45:37

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -23.906MHz



ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 22:22:54