



n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -38.01dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 10:57:39

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -40.83dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 22.SEP.2024 13:54:58

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -37.35dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 10:58:54

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.74dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 11:00:08

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.55dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 23.SEP.2024 22:38:47

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -38.10dBm




ProjectNo.:2401W26164E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 11:01:18


n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -40.70dBm




n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -41.30dBm




n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -40.95dBm




n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -40.62dBm




n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -40.49dBm



n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -41.36dBm




n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -40.91dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 22_SEP.2024 19:00:45

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -41.10dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 22_SEP.2024 19:01:45

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -41.04dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 22_SEP.2024 19:02:46

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -40.51dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 22_SEP.2024 19:03:44

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -41.23dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 22_SEP.2024 19:04:39

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -41dBm




ProjectNo.: 2401W26164E-RF Testert:Kungfamester Liang
Date: 22_SEP.2024 19:05:40

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -41.33dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:06:36

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -41.20dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:07:34

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -41.49dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:08:36

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -41.11dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:09:36

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -41.18dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:10:33

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.68dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:11:33

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -41.01dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:12:25

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -40.54dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:13:25

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -41.25dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:14:26

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -41.38dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:15:23

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -41.14dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:16:18

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -41.42dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:17:20

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -41.03dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:18:16

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -41.42dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:19:11

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -41.45dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:20:11

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -40.07dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:21:07

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -41.17dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:22:03

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -41.03dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:23:04

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -40.70dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:24:01

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -40.97dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:24:57

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -41.15dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:27:54

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -41.14dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:26:01

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -41.19dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:26:58

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -41.32dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:30:48

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -41.23dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:28:55

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -41.26dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:29:52

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -41.60dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:33:40

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -41.22dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:31:49

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -40.88dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:32:44

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -40.89dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:36:35

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -40.77dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:34:43

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -41.14dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:35:39

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -41.26dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:39:25

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -41.31dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:37:36

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -41.20dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:38:32

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -41.36dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:42:23

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@0 -40.95dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:40:31

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -40.53dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:41:27

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -40.91dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:45:15

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -40.97dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:43:26

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -41.26dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:44:23

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -40.88dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:48:17

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.30dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:46:24

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -41.27dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:47:21

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -40.87dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:51:11

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@0 -40.99dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:49:18

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -41.23dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:50:15

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -40.99dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:54:09

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -41.35dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:52:15

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -40.66dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:53:12

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -41.20dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:57:04

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -41.05dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:55:11

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -40.67dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 19:56:08

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -40.66dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfamester Liang
Date: 22_SEP.2024 20:00:00