




n77_2_10MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB24@0 8.572MHz




n77_2_10MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB24@0 8.568MHz




n77_2_10MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB24@0 8.612MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.463MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 13.456MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB36@0 13.463MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB36@0 13.460MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB36@0 13.465MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB38@0 13.566MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB38@0 13.580MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB38@0 13.575MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB38@0 13.529MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.004MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB50@0 18.102MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB50@0 18.009MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 18.018MHz




n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB50@0 18.023MHz




n77_2_20MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB51@0 18.165MHz



n77_2_20MHz_30kHz_3625MHz_CP-OFDM 64
QAM RB51@0 18.171MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK RB75@0 27.533MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM RB75@0 27.723MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB75@0 27.743MHz




n77_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB75@0 27.508MHz




n77_2_30MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB78@0 27.844MHz




n77_2_30MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB78@0 27.767MHz




n77_2_30MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB78@0 27.750MHz




n77_2_30MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB78@0 27.756MHz




n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.451MHz




n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 37.450MHz




n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB100@0 37.290MHz



n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB100@0 37.126MHz



n77_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB100@0 37.304MHz



n77_2_40MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB106@0 37.676MHz

