



n7

n7_5MHz_15kHz_2502.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.31dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:09:39

n7_5MHz_15kHz_2502.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.47dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:10:11

n7_5MHz_15kHz_2502.5MHz_DFT-s-OFDM
QPSK_RB25@0 -36.51dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:10:43

n7_5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0
-37.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:11:38

n7_5MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@24 -37.31dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:12:34

n7_5MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB25@0 -37.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:13:07

n7_5MHz_15kHz_2567.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.11dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:14:19

n7_5MHz_15kHz_2567.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.48dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:14:51

n7_5MHz_15kHz_2567.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:15:23

n7_10MHz_15kHz_2505MHz_DFT-s-OFDM
QPSK_RB1@0 -37.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:16:36

n7_10MHz_15kHz_2505MHz_DFT-s-OFDM
QPSK_RB1@51 -37.40dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:17:08

n7_10MHz_15kHz_2505MHz_DFT-s-OFDM
QPSK_RB50@0 -37.41dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:17:41

n7_10MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -37.57dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:18:53

n7_10MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@51 -37.11dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:19:26

n7_10MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB50@0 -36.93dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:19:58

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB1@0 -37.08dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:21:11

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB1@51 -37.07dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:22:08

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB50@0 -37.55dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:22:40

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.78dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:23:54

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.46dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:24:26

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB75@0 -37.28dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:25:23

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -37.25dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:26:36

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@78 -37.20dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:27:08

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB75@0 -37.39dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:27:40

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.38dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:29:18

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.30dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:29:50

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.75dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:30:23

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB100@0 -37.41dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:33:05

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB1@0 -37.62dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:31:36

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB1@105 -37.29dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:32:33

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB100@0 -37.55dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:35:23

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -36.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:34:18

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@105 -36.88dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:34:51

n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB100@0 -37.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:37:41

n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB1@0 -36.60dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:36:36


n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB1@105 -37.22dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:37:09


n12

n12_5MHz_15kHz_701.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.54dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:02:13

n12_5MHz_15kHz_701.5MHz_DFT-s-OFDM
QPSK_RB1@24 -45.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:02:32

n12_5MHz_15kHz_701.5MHz_DFT-s-OFDM
QPSK_RB25@0 -46.60dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:02:50

n12_5MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.47dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:03:52

n12_5MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB1@24 -46.03dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:04:10

n12_5MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB25@0 -45.94dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:04:28

n12_5MHz_15kHz_713.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.59dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:05:30

n12_5MHz_15kHz_713.5MHz_DFT-s-OFDM
QPSK_RB1@24 -46.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:05:57

n12_5MHz_15kHz_713.5MHz_DFT-s-OFDM
QPSK_RB25@0 -45.95dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:06:16

n12_10MHz_15kHz_704MHz_DFT-s-OFDM
QPSK_RB1@0 -46.80dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:07:14

n12_10MHz_15kHz_704MHz_DFT-s-OFDM
QPSK_RB1@51 -45.91dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:07:33

n12_10MHz_15kHz_704MHz_DFT-s-OFDM
QPSK_RB50@0 -46.54dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:07:51

n12_10MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.11dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:08:53

n12_10MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB1@51 -46.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:09:12

n12_10MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB50@0 -46.13dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:09:30

n12_10MHz_15kHz_711MHz_DFT-s-OFDM
QPSK_RB1@0 -45.86dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:10:30

n12_10MHz_15kHz_711MHz_DFT-s-OFDM
QPSK_RB1@51 -45.89dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:10:48

n12_10MHz_15kHz_711MHz_DFT-s-OFDM
QPSK_RB50@0 -45.77dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:11:07

n12_15MHz_15kHz_706.5MHz_DFT-s-OFDM
QPSK_RB1@0 -45.78dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:12:05

n12_15MHz_15kHz_706.5MHz_DFT-s-OFDM
QPSK_RB1@78 -46.11dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:12:48

n12_15MHz_15kHz_706.5MHz_DFT-s-OFDM
QPSK_RB75@0 -46.37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:13:07

n12_15MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -45.94dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:14:08

n12_15MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB1@78 -45.73dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:14:27

n12_15MHz_15kHz_707.5MHz_DFT-s-OFDM
QPSK_RB75@0 -46.45dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:15:10

n12_15MHz_15kHz_708.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.13dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:16:09

n12_15MHz_15kHz_708.5MHz_DFT-s-OFDM
QPSK_RB1@78 -46.52dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:16:28


n12_15MHz_15kHz_708.5MHz_DFT-s-OFDM
QPSK_RB75@0 -46.18dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 06:16:47


n38

n38_5MHz_15kHz_2572.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.61dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:38:51

n38_5MHz_15kHz_2572.5MHz_DFT-s-OFDM
QPSK_RB1@24 -36.95dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:39:23

n38_5MHz_15kHz_2572.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.15dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:39:54

n38_5MHz_15kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.34dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:40:49

n38_5MHz_15kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@24 -37.28dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:41:45

n38_5MHz_15kHz_2595MHz_DFT-s-OFDM
QPSK_RB25@0 -37.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:42:16

n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.36dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:43:25

n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.13dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:43:56

n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.44dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 8.AUG.2024 19:44:28

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM
QPSK_RB1@0 -37.23dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:38:57

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM
QPSK_RB1@23 -37.22dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:39:30

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM
QPSK_RB24@0 -37.32dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:40:03

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.20dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:41:01

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@23 -37.44dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:41:59

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB24@0 -37.29dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:42:33

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM
QPSK_RB1@0 -36.94dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:43:45

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM
QPSK_RB1@23 -36.16dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:44:19

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM
QPSK_RB24@0 -37.66dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:44:53


n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.97dBm




n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.81dBm




n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.54dBm




n38_15MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.39dBm




n38_15MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@37 -37.80dBm



n38_15MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB36@0 -36.93dBm




n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:50:50

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.64dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:51:24

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.50dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:51:57

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM
QPSK_RB1@0 -37.48dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:53:09

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM
QPSK_RB1@50 -37.17dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:53:43

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM
QPSK_RB50@0 -37.58dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:54:16

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.39dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:55:41

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@50 -37.17dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:56:15

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB50@0 -37.31dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:56:49

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@0 -37.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:58:01

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@50 -37.94dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:58:35

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB50@0 -37.21dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 07:59:08

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:00:06

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@64 -37.25dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:00:40

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB64@0 -37.37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:01:14

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.67dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:02:26

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@64 -37.37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:03:00

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB64@0 -36.64dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:03:33

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.65dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:04:48

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@64 -37.58dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:05:22

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB64@0 -37.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:05:56

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@0 -37.41dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:07:08

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@77 -37.32dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:07:42

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB75@0 -37.55dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:08:16

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -36.94dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:09:40

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@77 -37.76dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:10:14

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB75@0 -37.61dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:10:48

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@0 -37.95dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:12:03

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@77 -37.40dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:12:37

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB75@0 -36.83dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:13:11

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB100@0 -37.48dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:15:31

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@0 -37.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:14:23

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@105 -37.69dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:14:57

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB100@0 -37.24dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:18:58

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.20dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:17:50

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@105 -37.08dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:18:23

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB100@0 -37.33dBm




n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@0 -37.46dBm




n41


n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@105 -37.07dBm



n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@0 -36.91dBm



n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@23 -37.52dBm



n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB24@0 -37.15dBm

