



60MHz\_30kHz\_3840MHz\_DFT-s-OFDM 64 QAM\_RB162@0&amp;57.781 MHz




60MHz\_30kHz\_3840MHz\_DFT-s-OFDM PI/2 BPSK\_RB162@0&amp;57.721 MHz




60MHz\_30kHz\_3840MHz\_DFT-s-OFDM QPSK\_RB162@0&amp;57.726 MHz




60MHz\_30kHz\_3950MHz\_CP-OFDM 16 QAM\_RB162@0&amp;57.724 MHz




60MHz\_30kHz\_3950MHz\_CP-OFDM 256 QAM\_RB162@0&amp;57.733 MHz




60MHz\_30kHz\_3950MHz\_CP-OFDM 64 QAM\_RB162@0&amp;57.734 MHz




60MHz\_30kHz\_3950MHz\_CP-OFDM QPSK\_RB162@0&amp;57.748 MHz




60MHz\_30kHz\_3950MHz\_DFT-s-OFDM 16 QAM\_RB162@0&amp;57.689 MHz




60MHz\_30kHz\_3950MHz\_DFT-s-OFDM 256 QAM\_RB162@0&amp;57.781 MHz




60MHz\_30kHz\_3950MHz\_DFT-s-OFDM 64 QAM\_RB162@0&amp;57.749 MHz




60MHz\_30kHz\_3950MHz\_DFT-s-OFDM PI/2 BPSK\_RB162@0&amp;57.729 MHz




60MHz\_30kHz\_3950MHz\_DFT-s-OFDM QPSK\_RB162@0&amp;57.731 MHz




70MHz\_30kHz\_3735MHz\_CP-OFDM 16 QAM\_RB189@0&amp;67.330 MHz




70MHz\_30kHz\_3735MHz\_CP-OFDM 256 QAM\_RB189@0&amp;67.330 MHz




70MHz\_30kHz\_3735MHz\_CP-OFDM 64 QAM\_RB189@0&amp;67.380 MHz




70MHz\_30kHz\_3735MHz\_CP-OFDM QPSK\_RB189@0&amp;67.392 MHz




70MHz\_30kHz\_3735MHz\_DFT-s-OFDM 16 QAM\_RB180@0&amp;66.814 MHz



70MHz\_30kHz\_3735MHz\_DFT-s-OFDM 256 QAM\_RB180@0&amp;66.921 MHz




70MHz\_30kHz\_3735MHz\_DFT-s-OFDM 64 QAM\_RB180@0&amp;66.924 MHz




70MHz\_30kHz\_3735MHz\_DFT-s-OFDM PI/2 BPSK\_RB180@0&amp;66.883 MHz




70MHz\_30kHz\_3735MHz\_DFT-s-OFDM QPSK\_RB180@0&amp;66.874 MHz




70MHz\_30kHz\_3840MHz\_CP-OFDM 16 QAM\_RB189@0&amp;67.380 MHz




70MHz\_30kHz\_3840MHz\_CP-OFDM 256 QAM\_RB189@0&amp;67.379 MHz




70MHz\_30kHz\_3840MHz\_CP-OFDM 64 QAM\_RB189@0&amp;67.393 MHz




70MHz\_30kHz\_3840MHz\_CP-OFDM QPSK\_RB189@0&amp;67.389 MHz




70MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16 QAM\_RB180@0&amp;66.755 MHz



70MHz\_30kHz\_3840MHz\_DFT-s-OFDM 256 QAM\_RB180@0&amp;66.755 MHz




70MHz\_30kHz\_3840MHz\_DFT-s-OFDM 64 QAM\_RB180@0&amp;66.744 MHz




70MHz\_30kHz\_3840MHz\_DFT-s-OFDM PI/2 BPSK\_RB180@0&amp;66.804 MHz




70MHz\_30kHz\_3840MHz\_DFT-s-OFDM QPSK\_RB180@0&amp;66.751 MHz




70MHz\_30kHz\_3945MHz\_CP-OFDM 16 QAM\_RB189@0&amp;67.437 MHz




70MHz\_30kHz\_3945MHz\_CP-OFDM 256 QAM\_RB189@0&amp;67.375 MHz




70MHz\_30kHz\_3945MHz\_CP-OFDM 64 QAM\_RB189@0&amp;67.392 MHz




70MHz\_30kHz\_3945MHz\_CP-OFDM QPSK\_RB189@0&amp;67.429 MHz




70MHz\_30kHz\_3945MHz\_DFT-s-OFDM 16 QAM\_RB180@0&amp;67.094 MHz



70MHz\_30kHz\_3945MHz\_DFT-s-OFDM 256 QAM\_RB180@0&amp;66.712 MHz




70MHz\_30kHz\_3945MHz\_DFT-s-OFDM 64 QAM\_RB180@0&amp;66.824 MHz




70MHz\_30kHz\_3945MHz\_DFT-s-OFDM PI/2 BPSK\_RB180@0&amp;67.050 MHz




70MHz\_30kHz\_3945MHz\_DFT-s-OFDM QPSK\_RB180@0&amp;67.087 MHz




80MHz\_30kHz\_3740MHz\_CP-OFDM 16 QAM\_RB217@0&amp;77.342 MHz




80MHz\_30kHz\_3740MHz\_CP-OFDM 256 QAM\_RB217@0&amp;77.199 MHz




80MHz\_30kHz\_3740MHz\_CP-OFDM 64 QAM\_RB217@0&amp;77.288 MHz




80MHz\_30kHz\_3740MHz\_CP-OFDM QPSK\_RB217@0&amp;77.302 MHz




80MHz\_30kHz\_3740MHz\_DFT-s-OFDM 16 QAM\_RB216@0&amp;76.969 MHz




80MHz\_30kHz\_3740MHz\_DFT-s-OFDM 256 QAM\_RB216@0&amp;76.878 MHz




80MHz\_30kHz\_3740MHz\_DFT-s-OFDM 64 QAM\_RB216@0&amp;76.911 MHz




80MHz\_30kHz\_3740MHz\_DFT-s-OFDM PI/2 BPSK\_RB216@0&amp;77.018 MHz




80MHz\_30kHz\_3740MHz\_DFT-s-OFDM QPSK\_RB216@0&amp;76.979 MHz




80MHz\_30kHz\_3840MHz\_CP-OFDM 16 QAM\_RB217@0&amp;77.352 MHz




80MHz\_30kHz\_3840MHz\_CP-OFDM 256 QAM\_RB217@0&amp;77.194 MHz




80MHz\_30kHz\_3840MHz\_CP-OFDM 64 QAM\_RB217@0&amp;77.296 MHz




80MHz\_30kHz\_3840MHz\_CP-OFDM QPSK\_RB217@0&amp;77.337 MHz



80MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16 QAM\_RB216@0&amp;77.016 MHz




80MHz\_30kHz\_3840MHz\_DFT-s-OFDM 256 QAM\_RB216@0&amp;76.920 MHz




80MHz\_30kHz\_3840MHz\_DFT-s-OFDM 64 QAM\_RB216@0&amp;76.927 MHz




80MHz\_30kHz\_3840MHz\_DFT-s-OFDM PI/2 BPSK\_RB216@0&amp;76.927 MHz




80MHz\_30kHz\_3840MHz\_DFT-s-OFDM QPSK\_RB216@0&amp;77.031 MHz



80MHz\_30kHz\_3940MHz\_CP-OFDM 16 QAM\_RB217@0&amp;77.357 MHz



80MHz\_30kHz\_3940MHz\_CP-OFDM 256 QAM\_RB217@0&amp;77.243 MHz



80MHz\_30kHz\_3940MHz\_CP-OFDM 64 QAM\_RB217@0&amp;77.402 MHz

