



10MHz_Low_QPSK_1@0 -34.48dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:46:28

10MHz_Low_QPSK_50@0 -34.50dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:46:47

10MHz_Middle_QPSK_1@0 -34.10dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:47:07

10MHz_Middle_QPSK_50@0 -35.03dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:47:26

10MHz_High_QPSK_1@0 -34.91dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:47:45

10MHz_High_QPSK_50@0 -34.91dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:48:05


15MHz_Low_QPSK_1@0 -35.21dBm




15MHz_Low_QPSK_75@0 -34.74dBm




15MHz_Middle_QPSK_1@0 -35.31dBm




15MHz_Middle_QPSK_75@0 -34.89dBm




15MHz_High_QPSK_1@0 -34.12dBm



15MHz_High_QPSK_75@0 -34.42dBm




20MHz_Low_QPSK_1@0 -34.46dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:51:24

20MHz_Low_QPSK_100@0 -35.05dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:51:44

20MHz_Middle_QPSK_1@0 -34.60dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:52:05

20MHz_Middle_QPSK_100@0 -34.62dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:52:25

20MHz_High_QPSK_1@0 -34.83dBm



ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:52:46


20MHz_High_QPSK_100@0 -33.85dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:53:07

B41_2, Normal


2_5MHz_Low_QPSK_1@0 -34.96dBm




2_5MHz_Low_QPSK_25@0 -34.67dBm




2_5MHz_Middle_QPSK_1@0 -34.82dBm




2_5MHz_Middle_QPSK_25@0 -33.85dBm




2_5MHz_High_QPSK_1@0 -34.62dBm




2_5MHz_High_QPSK_25@0 -34.01dBm




2_10MHz_Low_QPSK_1@0 -33.91dBm




2_10MHz_Low_QPSK_50@0 -34.60dBm




2_10MHz_Middle_QPSK_1@0 -34.94dBm




2_10MHz_Middle_QPSK_50@0 -34.92dBm




2_10MHz_High_QPSK_1@0 -33.95dBm




2_10MHz_High_QPSK_50@0 -34.88dBm




2_15MHz_Low_QPSK_1@0 -35.01dBm




2_15MHz_Low_QPSK_75@0 -34.15dBm




2_15MHz_Middle_QPSK_1@0 -34.83dBm




2_15MHz_Middle_QPSK_75@0 -33.95dBm




2_15MHz_High_QPSK_1@0 -34.71dBm



2_15MHz_High_QPSK_75@0 -34.89dBm




2_20MHz_Low_QPSK_1@0 -34.72dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 01:00:12

2_20MHz_Low_QPSK_100@0 -35.14dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 01:00:13

2_20MHz_Middle_QPSK_1@0 -34.77dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 01:00:54

2_20MHz_Middle_QPSK_100@0 -34.21dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 01:01:15

2_20MHz_High_QPSK_1@0 -34.38dBm



ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 01:01:37

2_20MHz_High_QPSK_100@0 -33.33dBm



ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 01:01:58