



n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.44dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:40:13

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -47.58dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:41:15

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -47.58dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:42:16

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@0
-47.23dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:43:28

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -47.90dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:44:30

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -47.51dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:45:31

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@0
-47.49dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 12:46:40

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -47.52dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 12:47:40

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.67dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 12:48:38

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.74dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 12:49:44

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -46.99dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 12:50:43

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -46.81dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 12:51:43

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@0
-47.24dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:52:48

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.08dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:53:47

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -47.73dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:54:45

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@0
-47.48dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:55:59

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -47.79dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:57:01

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -47.29dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 12:58:04

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.36dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 12:59:11

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -47.92dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:00:14

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -47.13dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:01:17

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@0
-47.82dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:02:26

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -47.50dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:03:25

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -47.85dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:04:32

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@0
-47.27dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:05:40

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -47.65dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:06:40

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -47.25dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:07:41

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.51dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:08:45

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.19dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:09:46

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.56dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:10:46

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@0
-47.47dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:11:51

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -47.39dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:12:52

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.79dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 20.FEB.2025 13:13:55

n78_2
n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB1@0
-47.54dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:32:58

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB1@23
-46.98dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:33:55

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM QPSK_RB24@0
-47.20dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:34:53

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.30dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:35:55

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@23
-47.44dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:36:53

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB24@0
-47.22dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:37:50

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB1@0
-47.71dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:38:53

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB1@23
-46.97dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:39:50

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM QPSK_RB24@0
-47.27dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:40:47

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@0 -47.28dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:41:53

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@37 -47.09dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:42:51

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB36@0 -47.48dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:43:45

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.45dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:44:52

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@37
-47.09dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:45:45

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB36@0
-47.21dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:46:46

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@0 -47.67dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:47:45

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@37 -47.07dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:48:47

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB36@0 -47.15dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 03:49:45

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM QPSK_RB1@0
-47.87dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:00:57

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM QPSK_RB1@50
-47.41dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:01:56

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM QPSK_RB50@0
-46.96dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:02:54

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.63dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:03:57

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@50
-46.32dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:04:55

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB50@0
-47.39dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:05:55

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM QPSK_RB1@0
-47.67dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:06:59

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM QPSK_RB1@50
-47.41dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:07:58

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM QPSK_RB50@0
-47.34dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:08:56

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@0
-47.78dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:10:02

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB1@77
-47.65dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:11:01

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM QPSK_RB75@0
-47.63dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:12:14

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.22dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:13:17

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@77
-47.23dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:14:13

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB75@0
-47.44dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:15:10