



n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@0
-47.27dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:16:12

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB1@77
-47.25dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:17:09

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM QPSK_RB75@0
-47.75dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:18:06

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM QPSK_RB1@0
-47.17dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:19:13

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@105 -46.92dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:20:10

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB100@0 -47.29dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:21:07

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.27dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:22:10

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@105 -46.77dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:23:08

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 -47.65dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:24:05

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM QPSK_RB1@0
-47.38dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:25:13

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@105 -47.33dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:26:10

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB100@0 -47.41dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:27:08

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM QPSK_RB1@0
-47.38dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:28:14

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@132 -46.94dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:29:13

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB128@0 -47.04dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:30:10

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.48dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:31:13

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@132 -47.26dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:32:10

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 -47.72dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:33:08

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM QPSK_RB1@0
-47.68dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:34:17

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@132 -47.79dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:35:15

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB128@0 -47.53dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:36:13

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM QPSK_RB1@0
-47.20dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:37:19

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@161 -47.49dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:38:18

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB162@0 -47.02dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 04:39:17

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.46dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 21.FEB.2025 04:40:20

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@161 -47.78dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 21.FEB.2025 04:41:19

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 -46.95dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 21.FEB.2025 04:42:18

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM QPSK_RB1@0
-46.46dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 21.FEB.2025 04:43:21

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@161 -47.30dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 21.FEB.2025 04:44:20

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB162@0 -47.48dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 21.FEB.2025 04:45:18

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM QPSK_RB1@0
-47.39dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:46:25

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@188 -47.36dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:47:23

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB180@0 -47.32dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:48:22

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.63dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:49:32

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -47.23dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:50:31

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -47.66dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 04:51:29

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM QPSK_RB1@0
-47.60dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 08:09:13

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -47.40dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 08:10:16

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -47.50dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 08:11:20

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM QPSK_RB1@0
-47.34dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 08:12:34

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -46.25dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 08:13:38

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.37dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 08:14:02

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.38dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:15:05

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -47.64dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:16:09

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -47.35dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:17:05

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM QPSK_RB1@0
-47.52dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:18:13

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.44dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:19:13

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -47.43dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:20:13

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM QPSK_RB1@0
-47.77dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 21.FEB.2025 05:21:22

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -47.12dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 21.FEB.2025 05:22:21

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -47.21dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 21.FEB.2025 05:23:21

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.23dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 21.FEB.2025 08:14:50

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -47.41dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 21.FEB.2025 05:29:43

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -47.27dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 21.FEB.2025 05:30:42

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM QPSK_RB1@0
-47.50dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:31:45

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -47.29dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:32:49

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -47.32dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:33:45

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM QPSK_RB1@0
-47.60dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:34:57

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -47.80dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:35:56

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -46.76dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 05:36:56

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB1@0
-47.41dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 05:38:01

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.46dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 05:39:01

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -46.88dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 05:40:01

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM QPSK_RB1@0
-46.86dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 05:41:06

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -47.41dBm



ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 05:42:05

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.82dBm



ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang
Date: 21.FEB.2025 05:43:05