

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200

TEST CONFIGURATION PHOTOGRAPHS



Figure 1. Radiated Emissions Test Setup, 30 MHz to 200 MHz, Single Config

Note: 16-0215 is project number for testing performed in 2016

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 2. Radiated Emissions Test Setup, 30 MHz to 200 MHz, Dual Config

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 3. Radiated Emissions Test Setup, 200 MHz to 1GHz, Single Config

Note: 16-0215 is project number for testing performed in 2016

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 4. Radiated Emissions Test Setup, 200 MHz to 1GHz, Dual Config

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200



Figure 5. Radiated Emission Test Setup, above 1 GHz, Single Config

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 220
2AEP2-THAWK1
17-0097
June 13, 2017
Headsight, Inc.
HT5200




Figure 6. . Radiated Emission Test Setup, above 1 GHz, Dual Config