

Construction Tools PC AB

MDS label information

Labeling and location

2019-01-07

Document ID SCDOC-74-6	TITLE MDS label information		VERSION V0.4	DATE 2019-01-07
AUTHOR Henrik Sihm		DOCUMENT RESPONSIBLE Construction Tools PC AB	APPROVED BY	

1 OVERVIEW

MDS consists of three parts; one MDS sensor inside remote control and two MDS sensors inside the machine in which distance is measured to. All three are identical in terms of electronic HW and SW.

2 MACHINE SIDE MDS LABELLING INFORMATION

MDS on the machine side is placed inside a protective casing (see below). Outside this casing the following sticker will be placed



Figure 1: MDS with protective casing and label placement.




Figure 3: Label design and text.

Since the device is small then the text “This device complies...” is written in the user manual.