

A

B

C

D

E

F

G

A

B

C

D

E

F

G



WHAT TO DO WHEN THE ALARM SOUNDS

SILENCING THE LOW BATTERY WARNING

This silence feature can temporarily quiet the low battery warning "chirp" for up to 12 hours. You can silence the low battery warning "chirp" by pressing the Test/Hush button on the alarm cover.

Replace the battery as soon as possible, this unit will not operate without battery power!

REGULAR MAINTENANCE

To keep the alarm working properly, follow these simple methods:

- Test the alarm at least once a week to verify the unit's alarm and indicator are working properly.
- Clean the alarm annually by using compressed air or a vacuum cleaner hose. Never use water, cleaners or solvents since they may damage the unit.
- If the stroke alarm cannot be cleaned to avoid unwanted alarms, replace the unit immediately.
- When you hear the low battery warning ("chirp") approximately once every 54 seconds), please replace the battery immediately to continue your protection.

- (1) In all sleeping rooms and guest rooms.
- (2) Outside of each separate dwelling unit sleeping area, within 2 ft (614 mm) of any door to a sleeping room, with the distance measured along a path of travel.
- (3) On every level of a dwelling unit, including basements.
- (4) On every level of a residential board and care occupancy (smn facility), including basements and excluding crawl spaces and unfinished attics.
- (5) In the living area(s) of a guest suite.
- (6) In the living area(s) of a residential board and care occupancy.

(Reprinted with permission from NFPA 72B, National Fire Alarm and Signaling Code Copyright © 2012 National Fire Protection Association, Quincy, MA 02269. This reprinted material is not the complete and official position of the National Fire Protection Association. It is the property of the publisher and is intended only for the individual user. The subject which is represented only by the standard is in its entirety.)

(National Fire Alarm and Signaling Code® and NFPA 72® are registered trademarks of the National Fire Protection Association, Inc., Quincy, MA 02269.)

Statement

This device complies with Part 15 of the FCC Rules. Operation is subject to the following conditions:

1) This device may not cause harmful interference.

2) This device must accept any interference received, including interference that may cause undesired operation.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Note

This equipment has been tested and found to comply with the limits for a class B digital device pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment has been tested and found to comply with the limits for a Class B digital device pursuant to Part 15 of the FCC Rules, and its operation could cause interference to radio communications.

It is the responsibility of the user to ensure that this equipment does not cause harmful interference. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

尺寸：402*134mm,折叠后尺寸为67*67mm
材质：80g书纸
印刷：正反面单色印刷

注：包材需符合RoHS,REACH认证要求

