

Due to the size of the sample, the FCC ID information is shown on the manual and packaging.

Wireless Earbuds

Model: BTH101

SKU: D01-2652N-01

FCC ID: 2ALNA-BTH101

IC: 26717-BTH101

EU Importer:

Thousandshores Deutschland
GmbH, SorbenstraÙe 22, 20537
Hamburg, DE

UK Authorised Representative:

APEX CE SPECIALISTSLIMITED,
89PrincessStreet, Manchester,
M14HT, UK

Us Importer:

Thousandshores Inc.,
37707CherrySt, Newark,
CA 94560, USA

Manufacturer:

Shenzhen Thousandshores Technology
Co., Ltd Room T101, Building B, Lotus
Plaza, No. 3186 Nanshan Avenue,
Majialong Community, Nantou Street,
Nanshan District, Shenzhen, China

Thank you for choosing Tribit

Please be assured that we always stand
behind our brands, if you have any
questions regarding our products,
please feel free to contact us.

Made in China



Support@tribit.com

Submit support ticket on
tribit.com/support

Пожизненная техническая поддержка.

Наша гарантия является дополнением к законным правам потребителей при покупке этого продукта. Условия, исключающие **гарантийное обслуживание**:

1. Несанкционированное обслуживание, неправильное использование, столкновение, халатность, злоупотребление, попадание жидкости, несчастные случаи, изменения, неправильное использование аксессуаров, не являющихся оригинальными, или порванные/измененные этикетки, поврежденные знаки безопасности.
2. Истек срок гарантийного срока.
3. Ущерб, вызванный обстоятельствами непреодолимой силы.
4. Ущерб, причиненный по вине человека.

FCC Statement

FCC ID: 2ALNA-BTH101

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. This equipment complies