




PANTONE 877 C

- NOTES:
- 1. xx.xx INDICATES KEY INSPECTION DIMENSION.
 - 2. TOOLING SHALL BE PERMANENTLY MARKED "PROPERTY OF NURA"
 - 3. MATERIALS MUST BE ROHS AND REACH COMPLIANT

CUT		Marking	
Crease		Kiss cut	
V-miter		Reference	
Center Line		Pref cut	(5:5)
Wave		Adhesion	
Amendment		Fixed position	

SCALE 1:1 A3  Dimensions in Millimeters

Circled Dimensions On Drawing MUST BE INSPECTED	Dimensional Tolerances, Unless Otherwise Stated Are: Two Decimal Places= +/-0.05 One Decimal Place= +/-0.1 Zero Decimal Places=+/-0.5
---	---

Description:TBA
Part No. : NUR03-920-Certifications Sticker