



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 19:31:00

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 19:32:47

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 19:34:32

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 19:33:36

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 19:35:28

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 19:36:36

Band 2_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 19:38:15

Band 2_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 19:37:32

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 19:40:23

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 19:41:23

Band 2_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 19:43:04

Band 2_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 19:42:21

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 17:42:55

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 17:43:26

Band 2_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 17:43:48

Band 2_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 17:44:22

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 17:44:43

Band 2_15 MHz_Low_16QAM_RB75#0



Date: 4.NOV.2021 17:45:13

Band 2_15 MHz_High_QPSK_RB75#0




Date: 4.NOV.2021 17:45:43

Band 2 15 MHz High 16QAM RB75#0




Date: 4.NOV.2021 17:46:10

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 4.NOV.2021 17:46:36

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 4.NOV.2021 17:47:03

Band 2_20 MHz_High_QPSK_RB100#0




Date: 4.NOV.2021 17:47:36

Band 2_20 MHz_High_16QAM_RB100#0




Date: 4.NOV.2021 17:48:09

Band 4_1.4 MHz_Low_QPSK_RB6#0



Date: 4.NOV.2021 17:48:28

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 17:48:45

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 17:49:06

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 17:49:20

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 17:49:38

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 17:49:52

Band 4_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 17:50:07

Band 4_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 17:50:24

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 17:50:46

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 17:51:00

Band 4_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 17:51:15

Band 4_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 19:44:16

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 17:52:01

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 17:52:26

Band 4_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 17:52:54

Band 4_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 17:53:18

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 17:53:50

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2021 17:54:19


Band 4_15 MHz_High_QPSK_RB75#0




Band 4_15 MHz_High_16QAM_RB75#0




Band 4_20 MHz_Low_QPSK_RB100#0



Band 4_20 MHz_Low_16QAM_RB100#0




Band 4_20 MHz_High_QPSK_RB100#0




Date: 4.NOV.2021 17:56:35

Band 4_20 MHz_High_16QAM_RB100#0




Date: 4.NOV.2021 17:57:05

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2021 17:57:24

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2021 17:57:41

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2021 17:57:55

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2021 17:58:12

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2021 19:46:51

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2021 19:47:57

Band 5_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2021 19:50:02

Band 5_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2021 19:48:56

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 19:55:48

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 19:55:08

Band 5_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 19:57:53

Band 5_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 19:58:34

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 4.NOV.2021 18:00:42

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 4.NOV.2021 18:01:06

Band 5_10 MHz_High_QPSK_RB50#0




Date: 4.NOV.2021 18:01:28

Band 5_10 MHz_High_16QAM_RB50#0




Date: 4.NOV.2021 18:01:56

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2021 19:59:43

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2021 18:02:28

Band 7_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2021 20:01:06

Band 7_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2021 20:02:01


Band 7_10 MHz_Low_QPSK_RB50#0




Band 7_10 MHz_Low_16QAM_RB50#0




Band 7_10 MHz_High_QPSK_RB50#0



Band 7_10 MHz_High_16QAM_RB50#0




Band 7_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2021 18:05:12

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2021 18:05:36

Band 7_15 MHz_High_QPSK_RB75#0




Date: 4.NOV.2021 18:06:03

Band 7_15 MHz_High_16QAM_RB75#0




Date: 4.NOV.2021 18:06:27

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 4.NOV.2021 18:06:53

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 4.NOV.2021 18:07:23

Band 7_20 MHz_High_QPSK_RB100#0



Date: 4.NOV.2021 18:07:44

Band 7_20 MHz_High_16QAM_RB100#0



Date: 4.NOV.2021 18:08:14