



Please refer to following plots:

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:51:10

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:51:32

## Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:52:02

## Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:52:27

## Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:53:03

## Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:53:29

## Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:54:04

## Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:54:30

## Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:55:00

## Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:55:22

## Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:55:55

## Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:56:18

## Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:56:54

## Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:57:19

## Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:57:46

## Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:58:14

## Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:58:44

## Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:59:03

## Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 14:59:31

## Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 14:59:56

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:00:27

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:00:53

## Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:01:26

## Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:01:55

## Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:02:24

## Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:02:53

## Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:03:23

## Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:03:48

## Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:04:18

## Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:04:41

## Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:05:20

## Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:05:45

## Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:06:21

## Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:06:47

## Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:07:20

## Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:07:49

## Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:08:18

## Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:08:41

## Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:09:04

## Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:09:23

## Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:09:56

## Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:10:18

## Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:10:55

## Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:11:20

## Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:11:53

## Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:12:19

## Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:12:51

## Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:13:17

## Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:13:43

## Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:14:03

## Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:14:32

## Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:14:54

## Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:15:27

## Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:15:56

## Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:16:26

## Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:16:55

## Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:17:32

## Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:17:57

## Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:18:25

## Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:18:51

## Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:19:24

## Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:19:49

## Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:20:25

## Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:20:54

## Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:21:30

## Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:21:55

## Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:22:35

## Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:22:57

## Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:23:36

## Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:23:59

## Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:24:28

## Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.OCT.2021 15:24:51

## Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:25:21

## Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:25:49

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:26:13

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:26:45

## Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:27:14

## Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:27:34

Band 5 3 MHz Low QPSK RB15#0 1(30MHz-1GHz)




Date: 29.OCT.2021 15:28:03

Band 5 3 MHz Low QPSK RB15#0 2(1GHz-10GHz)




Date: 29.OCT.2021 15:28:25

## Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:29:01

## Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:29:30

## Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:30:05

## Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:30:24

## Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:30:54

## Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:31:16

## Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:31:39

## Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:32:02

## Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:32:34

## Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:33:00

## Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:33:40

## Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:34:06

## Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:34:33

## Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:34:55

## Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:35:26

## Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 29.OCT.2021 15:35:55

## Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:36:27

## Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:36:53

## Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:37:22

## Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:37:51

## Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:38:18

## Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:38:43

## Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:39:23

## Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:39:45

## Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:40:22

## Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:40:48

## Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:41:15

## Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:41:35

## Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:42:17

## Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:42:43

## Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:43:19

## Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:43:47

## Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:44:14

## Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:44:33

## Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:45:09

## Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:45:29

## Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.OCT.2021 15:46:02

## Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.OCT.2021 15:46:30

## Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 29.OCT.2021 15:47:00

## Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 29.OCT.2021 15:47:23